


Images

The following aerial images show different angles of this structure for your reference.



○ - Damaged Area



Report: 1723177
Claim:
5345033262PE1108145

This document is provided under License by EagleView Technologies to the requestor for their Internal Use Only subject to the terms and conditions previously agreed to by the requestor when they registered for use of EagleView Technologies Services. It remains the property of EagleView Technologies and may be reproduced and distributed only within the requestor's company. Any reproduction or distribution to anyone outside of the requestor's company without EagleView's prior written permission is strictly prohibited. All aspects and handling of this report are subject to the Terms and Conditions previously agreed to by the requestor.

5.



Window and downspout damage; tree limb penetrating roof

6.



terracotta roof ridge tiles

19.



limb penetrating roof

20.



large hole in roof (obscured by limb)