



SURVEY

IDENTIFICATION	BASE DATA	
Street Address: 514 First Street	Historic Name: Perley House	
Map and Parcel: 33-17	Date/Period: 1889	
Census Track & Block: 3-506	Style: Victorian Vernacular	
Present Owner: Charles Camby	Height to Cornice:	
Address: 514 First Street	Height in Stories: 2	
Present Use: Residence Original Owner: James Perley	Present Zoning: R-3 Land Area (sq.ft.): 34.4 x 211	
Original Use: Residence	Assessed Value (land + imp.): $1500 + 4470 = 5970$	
ARCHITECTURAL DESCRIPTION This structure is one of three simple residences originally built of clapboard, now covered with aluminum shingles. The house is two stories high with a single story veranda decorated with gouged floral designs. Also present in this typical house is the popular two story bay window.		
HISTORICAL DESCRIPTION The lot was purchased in 1886 by James Perley for \$700 from the debt-ridden A.P. Abell (ACDB 88-179). In the deed the lot is referred to as the "Southern half of the Garden Lot" which was a part of the Abell lawn. The present structure was standing, along with its companions by 1889, which the tax records indicate that \$3,250 worth of improvements were contained on Perley's lot. Deed references: ACDB 88-179, City Will Book 1-385, DB 211-30, 212-23.		
GRAPHICS		
GRAFTIUS		
CONDITIONS	SOURCES	
Average	City/County Records	

LANDMARK COMMISSION-DEPARTMENT OF COMMUNITY DEVELOPMENT

INSPECTION SHEET

Board of Architectural Review Maintenance and Repair Inspection NOVEMBER, 1980

PROPERTY ADDRESS/Comments		SPECIFIC MAINTENANCE OR REPAIR ITEM
504 N First St		deterioration of exterior walls or other verticle supports;
Est West & North	b)	deterioration of roofs or other horizon- tal members;
Et West & North side gotters need replacing.	c)	deterioration of exterior chimneys;
	d)	deterioration or crumbling of exterior plaster or mortar;
	e)	ineffective waterproofing of exterior walls, roofs, & foundations including broken win- dows or doors;
will need extern paint	£)	peeling of paint, rotting, holes or other forms of decay;
	g)	lack of maintenance or surrounding environ- ment e.g. fences, sidewalks, gates, steps, signs, accessory structures & landscaping;
	h)	deterioration of any other feature which may permit hazardous or unsafe conditions.

Street Address: 514 (STSt. Lep & Parcol: 33-17 Concus Freet & Block: Present Owner: Mr Charles Carby Address: 514 (St. North) Present Use: Original Owner: Original Use:

Historic F Me: Data/Pariod: 1889 Style: Que Anne Venac. Height to Cornico: Height to Storics: Present Soning: Land Are (s. ft.): 44.4 ×211 Assessed Value (Land+imp) 90 × 2400 = 3396

shinaler aluminum province Description ballustred 1 story 3 bay beranda of champered posts of gaug Zstory bay window gable follreet

Came Holcombe Campbell-Hisrtoric Description 1959 Reer ly property - James Mundayó w

Invervieed:

Marcon

33-17 Holember Completel cuy from many Parkey (Co. 88-179 C1 W.B. 1-385 1959 . 211-30 Canby 1959 - 212-23 П___ \$ 11,500 1959 · Camby Scom Holcombe Campiel - 11,500 - 0.B. 212 - P.23 211 - P. 30 People's National Bonk 1959 Cambell from WB 1-385 Jan. 1915 Mary Porley from Jones Porley Jonnes Perley from A.P. Abell "Souther holf ACOB 88-179 Lot 106 wide A 700 - 1886 Lot 106' wides D to g. Vencent Parley 2 Rots conveyed by Many V. Perlay -DB 28 p. 385 - May 19/6 2) ANNIE E. Gleasons 53-396 -PLAT 28-385 . May , 1916 Hard Book - 1915 Mary Perley. 3 lotes with \$500 w/ \$1,100 improvements 1914 - Same property listed under games Regulars Dame 1899- 3 House valued at \$4000 1889 \$ 3250 worth of emprovements. on the lot.

NINENT: PENHISED 37×102 E-3 480+2100-2670 522=33-115





514 N 1st St.