Architectural Survey Form

Other DHR ID: No Data

DHR ID: 104-5841

## **Property Information**

**Property Names** 

Name Explanation Name

Function/Location House, 1025 Grady Avenue

**Property Evaluation Status** 

**Property Addresses** 

Current - 1025 Grady Avenue

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

## **Additional Property Information**

Architecture Setting: Urban
Acreage: No Data

**Site Description:** 

January 2020: This two-story house is located on the north side of Grady Avenue between 11th Street NW and 10 1/2 Street NW. There is a white picket fence along the front (southwest) property line, bushes and a paved driveway to the northwest of the house, and a large tree in the rear of the property. There is a one-story shed to the north of this property. This property consists of a house and a shed.

#### **Surveyor Assessment:**

January 2020: According to Charlottesville City Property Records, this house was constructed in 1937 (City of Charlottesville GIS Viewer 2020). This is supported in the Sanborn Maps, since the house does not appear in the 1929 Sanborn Map, but it is present in the 1950 map with the same footprint it has today (Sanborn Map Company 1929; Sanborn Map Company 1950; USGS 2017). The front and rear porches, which are open in the Sanborn Maps, have since been enclosed, but the dates are not clear on aerial photographs. The house had a garage to the northwest of the property in the 1950 Sanborn Map (Sanborn Map Company 1950). There is a garage in this location today that appears to have a larger footprint than the one in the Sanborn Map, but the date of expansion is not known (Sanborn Map Company 1950; NETR 1963; USGS 1994). The garage now functions as a shed.

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship for this property have been mildly compromised by replacement cladding, the enclosure of the front and rear porches, and replacement windows. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

### **Primary Resource Information**

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1937

Date Source: Local Records

**Historic Time Period:** World War I to World War II (1917 - 1945)

**Historic Context(s):** Domestic **Other ID Number:** *No Data* 

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5841

Architectural Style:VernacularForm:SquareNumber of Stories:2.0Condition:GoodThreats to Resource:None Known

#### **Architectural Description:**

January 2020: This two-story house sits on a stuccoed foundation, is clad in aluminum siding, and has a hipped roof covered in standing seam metal. There is an interior brick chimney on the northwest roof slope. The southwest (front) facing façade features a one-story, full-width, enclosed porch with a hipped roof, that is accessed by wood stairs. The majority of the windows have fixed wood shutters. The northeast (rear) elevation has a one-story wing with a front-gabled roof in the center and an enclosed porch on the northwest end. Visible fenestration includes three-over-three, double-hung, vinyl windows; one-over-one, double-hung, metal windows; four-over-four, double-hung, vinyl windows; and a single-leaf, wood door with a metal storm door.

#### **Exterior Components**

Component Component Type Material **Material Treatment** Chimneys Foundation Interior Slope Solid/Continuous Brick Strecther Bond Unknown Stuccoed/Parged 1-Story Full-Width Porch Aluminum Screened/Enclosed Structural System and Wood Frame Aluminum Siding

Exterior Treatment

Windows Double-hung Vinyl No Data Roof Hipped Metal No Data

# **Secondary Resource Information**

### Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 1937Date Source:Map

**Historic Time Period:** World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: Square
Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

# **Architectural Description:**

January 2020: There is a one-story shed to the north of the house. The shed is constructed of cement block and has a shallow, side-gabled, asphalt shingled roof with a rear shed roof extension. Visible fenestration includes a single-leaf, plywood door; and sliding plywood garage doors. However, this building does not appear to function as a garage anymore.

## **Exterior Components**

 Component
 Component Type
 Material
 Material Treatment

 Foundation
 Solid/Continuous
 Concrete
 Block

Foundation Solid/Continuous Concrete Block Structural System and Masonry Concrete Block Exterior Treatment

Roof Side Gable Asphalt No Data

## **Historic District Information**

Historic District Name:No DataLocal Historic District Name:No DataHistoric District Significance:No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form

DHR ID: 104-5841 Other DHR ID: No Data

#### **CRM Events**

# **Event Type: Survey:Phase I/Reconnaissance**

**Project Review File Number:** No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

#### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Bibliographic Information**

## **Bibliography:**

No Data

### **Property Notes:**

No Data

Page: 3 of 3 May 21, 2020

