



replacement window systems which would be more compatible with the building. One system to consider is the Pella System which have individual window lights.

Mr. Sellers and the owner Mr. McQueery also discussed with the Board various methods of cleaning the building. After a brief discussion Mr. Smith made to motion that every effort be made to restore the existing windows on the ground level and in the event the windows cannot be saved, then the Board would consider alternative window replacement systems. Also to approve the use of a light wash to clean the brick on this building. The motion was seconded by Mr. Allen and unanimously passed by all members present.

There being no further business, the meeting was adjourned at 8:45 a.m.