CERTIFICATE OF APPROPRIATENESS APPLICATION



Please Return To: Department of Neighborhood Planning and Development Services

P. O. Box, 911, City Hall

Charlottesville, Virginia 22902

Telephone (804) 970-3182; Fax (804) 970-3359

A.	Information on Property Applied For:	C. <u>P</u>	roperty Owner Information (If not applicant)
,, Addres	NEIGHBORHOOD DEVELOPMENT SERVICES SERVICES	Name	: Main Street Associates
	22902 ex Map No.: 29 Parcel: 20		(B) 434, 293, 2984 (H)
Address Phone: email E.	Avoid having to come back to the board for sulfive posed Work. List attached information (Drawings and States Frust be approved by the Department)	Necessa esequent ite Plan	Federal Tax Credits: Do you intend to apply for Federal Historic Preservation tax credits for this project?(y)X(n). (Please note that approval of this application does not assure certification of rehabilitation work for Federal preservation tax incentives. ary) - Please provide complete information in order to approval. See attached "Describme" approval. See attached "Describme" approval. See attached "Describme" and Description of Please note that site aborhood Planning and Development Services before the Photo (Sketch Package Attached
G.	. Property Owner Permission (If Not Application)	i <u>nt)</u>	H. Signature of Applicant
I have	read this application and hereby give my conse	nt	I hereby attest that the information I have provided is, to the best of my knowledge, comect.
Signal	Ure Date	_	Marie 19/7/03 Date
Rece	R OFFICE USE ONLY eived By: App Cor	rovad: _	Disapproved:

LANDMARK



SURVEY

CITTLE

IDENTIFICATION

Street Address: 105 Ridge Street

Map and Parcel: 29-20

Census Track & Block:

Present Owner: Mt. Zion Baptist Church

Address:

105 Ridge Road

Present Use:

Religious

Original Owner: Mt. Zion Baptist Church

Original Use:

Religious

BASE DATA

Historic Name:

Mt. Zion Baptist Church

Date/Period:

1878

Style:

Victorian Vernacular

Height to Cornice: Height in Stories: 2

Present Zoning:

Land Area (sq.ft.): 7165 sq. ft.

Assessed Value (land + imp.): 6180 + 12,270 = 18,450

ARCHITECTURAL DESCRIPTION

The church is a fairly elaborately detailed brick building that expresses well the late nineteenth century Virginia brick vernacular style of construction for larger buildings. It is basically a rectangular building with a moderately sloped metal gable roof with the gable end facing the street. From this end projects a central square brick tower. The brick tower rises to about ten feet above the level of the roof ridge creating a base, surrounded by a wooden cornice, that also surrounds the church just below the roof line, from which the spire rises in two stages. The first is an octagonal shingled base, with single shutter ventilation windows with small wooden pediments in each side. The second part of the spire is the eight sided roof spire that is crowned with a large finial point. The tower has a double round arched entrance door on the first floor level and several recessed panels. The upper edge of these panels is supported by a corbel design in brick similar to that found between the pilasters or shallow butresses that progress around the building, forming a brick antae effect at the corners. There are seven of these vertical strips on each running from the water table to just below the cornice, creating six bays each containing a tall round arched stained galss window. Below each of these is a shallow arch basement window. On the front a similar shal low buttess on either side of the tower runs to the roof cornice and the bays created contain an arched window on each side like those on the sides, but with a small stone keystone. A half window of equal height and proportion is centered over the entrance.

HISTORICAL DESCRIPTION

The congregation of the Mt. Zion Baptist Church was organized in 1867. The church met in houses of various members until 1878 when the land was purchased from the widow of Samuel White, in whose house the church had frequently met. The present church building, designed by George Spooner, was built in 1878. Because Samuel White's children were not of age when he died the title to the land was not cleared until 1894. The first pastor was the Rev. Spotswood Jones. The present minister is only the twelfth in its history and there is a congregation of about 650.

GRAPHICS

CONDITIONS

Very good

UTM: 17/720650/4211895

SOURCES

Zion Baptist Church, 100th anniversary publication, 1967.

RBGC

Architecture . Research . Urbanism 206 East Market Street . Charlottesville, VA 22902 . tel: 434.295.8352 . fax: 434.295.8627

Date:

10.71.03

Project:

Music Resource Center

105 Ridge Street

Re:

BAR Application Description of Proposed Work

1) Paint roof and all existing woodwork. Colors to match existing (Brick red roof and white woodwork)

2) Replace existing plexiglass protective panels over stained glass windows with new clear Lexan panels (See Photo #8). New panels to be bolted into wood frame within the round brickmould in the same manner as existing.

3) Install fixed metal security grates on 9 basement windows, 2 on front of building flanking the entry tower, 2 on the south façade and 5 on the north facade, as indicated on drawings. Grates to be wrought iron painted black. New grates to have 3 horizontals, with middle horizontal located to match the middle of Double Hung Windows. (Sketches #10A and #14A)Grates to be bolted into existing window frame (onto flat surface within round brickmould) to match the existing gates on building (see photo #11).

4) Replace existing double flush wood entry doors to basement in South Alley (See Photo#7) with new wood and glass door with transom and sidelite. (See Sketch #7A). Door to be one lite over wood panel with matching sidelite and 4 lite transom, as manufactured by Weathershield. New doors will be set at interior of masonry wall, exposing existing wood paneling on jamb faces (similar to existing paneling on Door in Photo #14). This will allow the new door to swing out as required by code, without projecting (beyond allowable) into the accessible. (See Plan of Ramp on Drawing)

Remove existing double doors in Basement on North Alley (See photo #14 and #15) and install new double hung window (see sketch #14B.New window to be wood 3 over 3 double hung window with true divided lites and insulated glass, as manufactured by Weathershield, (See photo #14B) Configuration of this window (3 over3) is to match existing adjacent windows (See Photo #10). Existing opening to be filled with masonry and receive application of stucco wainscot to match adjacent (Note that all new masonry will be covered with stucco). New window will be installed in the same relation to wall as existing windows, and with an new sill to match existing. (See Photo #16 and Sketch #16A) Photos #12 and #13 illustrate how hidden this new window is from view.

Install new ADA accessible ramp in South Alley for access to Basement. (See Drawing BAR 1.1), and replace existing stair to basement with new stair to meet code. New ramp and stairs to be concrete with wrought iron railing painted black. This is consistent with existing security gates and harmonious with existing historic fence. Note that both ramp and stair are completely below grade and begin approx 36" in front of building façade (this was necessary in order to achieve treads of stair to meet code). Photos # 3 ,#4 and #5 and Sketches #4A and #5A illustrate that the new ramp and stair railings will be only partially visible from the street and sidewalk.

RBGC

Architecture . Research . Urbanism 206 East Market Street . Charlottesville, VA 22902 . tel: 434.295.8352 . fax: 434.295.8627

Date:

10.71.03

Project:

Music Resource Center 105 Ridge Street

Re:

BAR Application Historical narrative

The Mt Zion Baptist Church, located at 105 Ridge Street is a brick structure, built in 1884, and is listed on the Virginia Register of Historic Buildings. The style and detailing of the church is typical of the late Victorian Period. According to an article in the September/October 2003 "Commercial Real Estate Weekly", the church is "constructed in the Gothic Revival Style". However the use of round arches with keystones, corner pilasters, overhanging eaves and decorative brickwork might suggest a better description to be Vernacular Victorian Style. This same article quotes Prof. Ed Lay as referring to the church as one of the grander black churches". The steeple, organ and stained glass windows were added in the 1890's.

The front yard of the church is bounded by a delicate black painted wrought iron fence with two gates and decorative arch and dagger detailing. The building itself is red brick in a running bond pattern, with a water table marked by corbelled brick. Decorative brickwork also appears in (blank) panels at the top of the steeple. Details typical of the period include a standing seam metal roof, arched windows with round brickmoulding, and a heavily paneled double front door with what appears to be original hardware. Of particular note are the arched stained glass transom over the front door reading "Mt. Zion Baptist Church Organized 1867", and the 12 round arched stained glass windows in a design of green, yellow and dark red glass.


The structure consists of a Entry Tower with steeple, with steps leading up to a foyer and the main Sanctuary on the first floor, with a balcony (no longer in use) and a basement below

A plaque placed at he church by the City last year reads:

"The origin of Mount Zion Baptist Church is traced back to the period after the Civil War. Although the founding fathers had roots in the White Baptist Church, in 1867 they began meeting independently from house to house. Soon thereafter, Brother Samuel White offered his home as a permanent meeting place. Around 1875 the congregation erected a frame church on Ridge Street that they called The Mount Zion First African Baptist Church of Charlottesville. In 1883, this church was razed, and in 1884 it was replaced with the current brick edifice, designed by George Wallace Spooner.

"The Church's founding minister was Spotswood Jones. Several of the subsequent ministers have been prominent community leaders, including the Reverend Alvin Edwards, who was Mayor of Charlottesville from 1990 to 1992.

"Hosting many prominent national speakers and leaders, Mount Zion Baptist Church has been influential in Charlottesville history, especially in the struggle for civil rights. Rose Hill Baptist, Ebenezer Baptist and Zion Union Baptist all came out of Mt. Zion Baptist Church,"




LOCATION MAP

MUSIC RESOURCE CENTER

PRE-APPLICATION MG / B.A.E.

11/5/03

PBGC.



SITE INFORMATION



PERMACOLOR 3500 SELECTOR

26 Gauge, Standard 35 Yr. Color Coatings Full Strength, 70% Kynar 500°/Hylar 5000°



Matte Black



Dark Bronze



Mill Finish (Galvalume-Plus®)



Colonial Red



Charcoal Gray



Slate Gray



Slate Blue




Forest Green



Hartford Green


Standard colors available on steel and aluminum, 26 ga. steel in stock at all times.


Colors shown are printer's representations. There may be very slight variations on actual metal. Ask for Englert's metal chips for specific colors.



105 Ridge Street Music Resource Center





















YIEW FROM CORNER OF SOUTH ST. AND WEST MAIN ST. HORTHEAST




2) VIEW OF BUILDING FROM SOUTH ON 5th St. 5806E

MUSIC RESOURCE CONFER 105 RIDGE ST. BAR PRE-APP. CONFERENCE 11/5/03 REGC



3 VIEW OF HEW PAMP/ ACCESSIBLE ROUTE LOCATION FROM SIDEWALK

MUSIC RESOURCE CONTECT PRE-APP. CONF.




TYIEW OF HEW RAMP MAKEMANN ACCESIBLE FOUTE LOCATION FROM SIDEWICK.

MUSIC RESOURCE CENTER 105 RIPGE ST.

B.A.F. PRE-LAPR CONFERENCE


1115/03 FBEC



Music resource comes 105 ROGEST.

B.A. F. ME- HP.

11/5/03 PAGC





BYSTILL DOOR TO BE REPLACED.

105 PLOGE ST MUSIC RESOURCE CEMPER

B. S.R. PRE-AN. CONF.

11/9/03 PBGC






BY VIEW INTO SOUTH AMEY FROM SIDEWALK.

MPC - 105 PIDGE ST

BAR MIG. 11/5/03

PLB GC






MRC . 105 RIDGE ST

BAR MG. 11/5/03

RBGC




(7A)

VIEW OF HEW ENTRY book.

MUSIC RESOURCE COMPER 105 PLOGE ST

BAR MG. 11/5/03

12136C



B EXISTING STAINED GLASS WILLDOW.
PROTECTIVE PANEL TO BE REPLACE WITH HEW LEXA PANEL.

MRC . 105 RIPGE ST BAR MTG. 11/5/03




(HEN SECURITY GME)

MUSIC RESOURCE CEMPER LOS RIDGE ST

BAR MITS 11/5/03

PEGC.



HEW SECURITY GATE ON FRONT WILLDOW

MUSIC RESOURCE CENTER

BAR MTC. 11/5/03




10) TYPICAL EXISTING SIDE BASEMENT WILLOW

(NEW SECURITY GATE)

MUSIC RESOURCE CENTER 105 RIPGE ST

BAR MTG. 1115/03

RBGr.




10A) TYPICAL SECURITYGATE
OVER BASEMENT WANDOW

MUSIC RESOURCE CEMENL 105 HDGE ST

BAR MIG. 11/5/03


KBGC.



EXISTING SECURITY GRATE (HEW TO BE SIMILAR).

MRC - 105 RIDGE ST

BAR PREATP. CONF 11/5/03 RBGC



12 YIEW INTO HORTH ALLEY FROM FRONT YARD


MRC - 165 C10GE ST BARMTE 11/5/03 P3GC



VIEW INTO ALLEY @ HEW WINDOW


13

MRC. 105 RIDGEST BAR MTG US (03



14) YIEM OF HEW WINDOW
FROM HORTH AWEY


MRC - 105 R1066 ST BAR MTG. 11(5/03 RRGC



(14 VIEW OF HEW WINDOW W/ SECURITY GARE.


MRC . 105 121065 ST

BAR MTG. 11/5/03.



MRC - 105 MOGE ST BAR MGC. 11/5/03


MAGC.



15) YIEN OF EXISTING
DOOR TO BE REMOVED
(FROM INTERCORY).


MRG. - 105 MAGE ST BAL MTG 4/5/03

RAGC





(6) YIEW OF HEW AND EXISTING WINDOW IN HORTH AVEY

> MLC 105 LIDGE ST BALL MTG 11/5/03



RB6C





Scala, Mary Joy From: Marthe Rowen [m rowen@earthlink.net] Sent: Wednesday, November 12, 2003 3:00 PM To: Scala, Mary Joy Subject: Re: BAR project Music Resource Center Mary Joy -One additional note: Martin Horn pointed out that the new "wrought iron" fence, will in fact be "painted steel to match historical wrought iron fence". I will get back to you on alley grade issue. Marty ---- Original Message ----From: "Scala, Mary Joy" <scala@charlottesville.org> To: "Marthe Rowen" <m rowen@earthlink.net> Sent: Wednesday, November 12, 2003 9:55 AM Subject: RE: BAR project Music Resource Center > I went and looked at it this morning. I would be interested in seeing what > the final product will look like - perhaps a sketch will do. > I am attaching the staff report and agenda FYI. <<03-11-07 105 Ridge > Street.doc>> <<AGENDA for 11-18-03.doc>> > Also, I need to post a notice on the property - you can do it, or I'll just > tape it to the fence. > Mary Joy Scala, Neighborhood Planner > Department of Neighborhood Development Services > City of Charlottesville > City Hall - P.O. Box 911 > Charlottesville, VA 22902 > PH 434-970-3182 > FAX 434- 970-3359 > scala@charlottesville.org > >> -----Original Message-----> > From: Marthe Rowen [SMTP:m_rowen@earthlink.net] > > Sent: Wednesday, November 12, 2003 9:43 AM > > To: Scala, Mary Joy > > Subject: Re: BAR project Music Resource Center > > > > Mary Joy -> > > > The answers to your three questions: > > >> 1) The question of bars over the glass doors is one we have discussed > > because, they would like to have visibility, but obviously need security. > > We

> > have decisded to not have grates over the doors. (It is possible that we

> > will work out some kind of interior security system)

> >

1

```
> > 2) The other windows will be covered from the inside with acoustic
walls,
> > so
> > do not present a security problem.
>>
> > 3) Yes we will raise the level of the alley, If you would like, I will
>> prepare a sketch and take some more photos of the existing condition (It
> > covered with construction ramp the day I took the pictures I submitted),
> > either send them over to you, or bring them to the meeting.
> > I am meeting with the contractors later this morning and will get more
> > specific information.
> >
> > Marty
>> ---- Original Message -----
> > From: "Scala, Mary Joy" <scala@charlottesville.org>
> > To: <m_rowen@earthlink.net>
> > Sent: Tuesday, November 11, 2003 3:57 PM
> > Subject: BAR project Music Resource Center
> >
> >
> > > Marty.
>>>
> > I thought of three questions as I was writing the staff report:
>>>
>>> Will the new door on the the south alley need have bars on the glass?
> > You are calling for 2 window grates on the south side - but aren't
there
>>5
>> existing windows?
>>>
>>> Are you still intending to fill the areaway on the north side to raise
> > the
> > > grade?
>>>
>>> Thank you.
>>>
> > Mary Joy Scala, Neighborhood Planner
> > Department of Neighborhood Development Services
>> City of Charlottesville
> > City Hall - P.O. Box 911
>> Charlottesville, VA 22902
>>> PH 434-970-3182
> > FAX 434- 970-3359
>> scala@charlottesville.org
>>>
>>>
> >
```

Scala, Mary Joy

From:

Scala, Mary Joy

Sent:

Tuesday, November 11, 2003 3:58 PM

To:

'm_rowen@earthlink.net'

Subject:

BAR project Music Resource Center

Marty,

I thought of three questions as I was writing the staff report:

Will the new door on the the south alley need have bars on the glass?

You are calling for 2 window grates on the south side - but aren't there 5 existing windows?

Are you still intending to fill the areaway on the north side to raise the grade?

Thank you.

Mary Joy Scala, Neighborhood Planner
Department of Neighborhood Development Services
City of Charlottesville
City Hall - P.O. Box 911
Charlottesville, VA 22902
PH 434-970-3182
FAX 434- 970-3359
scala@charlottesville.org