

VIRGINIA HISTORIC LANDMARKS COMMISSION

File no. 104 70 Negative no(s).

SURVE	SURVEY FORM		
Historic name	Common name		
County/Town/City Albermarle/Charlotte	cville		
Street address or route number 116-118 Chan-	collo-		
USGS Quad Charlottesville West, Ya			
Original owner	Date or period		
Original use	Architect/builder/craftsmen		
Present owner			
Present owner address	Source of name		
rresent owner address	Source of date		
Present use	Stories		
	Foundation and wall const'n		
Acreage			
State condition of the	Roof type		
State condition of structure and environs			
State notantial threats to			
State potential threats to structure			
Note any archaeological interest			
Should be investigated as			
Should be investigated for possible register potentia	1? yes no		
Architectural description (Note significant features	of plan, structural system and interior and exterior decoration,		
and to both out aspects not vising on clear	Trom photographs Explain makes 1 1 c 11 t		
and additions. List any outbuildings and their appro	ximate ages, cemeteries, etc.)		
Parking lot, for bank.	agos, cometerios, etc.)		
1 all tall 101, 401 Duils.			
**			
Interior inspects 19			
Interior inspected?			
Historical significance (Chain of title; individuals, far	milies, events, etc., associated with the property.)		
	A post propose reducers and propose grant and propose grant		

Sources and bibliography	
Published sources (Books, articles, etc., with bibliographic data.)	
the section \	
Primary sources (Manuscript documentary or graphic materials; give location.)	
Names and addresses of persons interviewed	
Plan (Indicate locations of rooms, doorways, windows, alterations, etc.)	
Figure (indicate locations of rooms, doorways, white wy	
Site plan (Locate and identify outbuildings, dependencies and significant topographical features.)	
Name, address and title of recorder B.L. Boshen V. of Da Grad. Student	Date
B.L. Boshen V. of Da Grad. Student	3-7-80


Vig Da Grad. Student



VIRGINIA HISTORIC LANDMARKS COMMISSION

File No. 104 - 130
Negative no(s), 7297

Town/City Charlotte			5-			
distoric name		Common name V	NB parking lot			
□ stone (□ rando	ing:	urse American, rsed ashlar, num, bricktex, c)		
Number of Stories Roof Type		Roof Material				
□ 1 □ 2½ ` □ 1½ □ 3 □ 2 □ □	gable		☐ slate ☐ wood shingle ☐ composition ☐ standing seam meta ☐ other			
Dormers Number of bays — Main facade						
□ 0 □ 3 □ she □ 1 □ 4 □ gat □ 2 □ □ □ pec	= mpped	□ 1 □ 2 □ 3	□ 5	□ 7 □ 8 □		
Porch S	itories	Bays	General de	scription		
☐ yes ☐ no ☐ 1 ☐ 2	□ 3 □ 1 (center) □ 1 (side)	□ 2. □ 4 □ 3 □ <u>-</u>		,		
Building type detached house detached town house row house double house	☐ garage☐ farmhouse☐ apartment building☐ gas station☐	government commercial commercial railroad	(office) School	g lot		
Style/period	Date	Archited	et/builder	0		
ocation and description of entra	Miscel cornic	e/eave type, window typ	mation (plan, exterior and inter e and trim, chimneys, additions on inclined terrac Elliewood Ave.	s, alterations)		



Historical information

Source

Surveyed by Jeff O'Dell, VHLC

Date 9-83