

VIRGINIA HISTORIC LANDMARKS COMMISSION

HISTORIC DISTRICT SURVEY FORM

File No.104-136 S/ Negative no(s). 7297

Street address 128 Chancello			
Town/City Charlottesvil	le		
Historic name		Common name	
☐ stone (☐ random rubt	nish, 🗀 stretcher, 🗀co ble, 🖂 randomashlar, 🖂 cou	rsed ashlar, inum, in	
Number of Stories	D4T		
1	☐ gable ☐ pediment ☐	mansard gambrel parapet flat	Roof Material ☐ slate ☐ tile ☐ wood shingle ☐ pressed tin ☐ composition ☐ not visible ☐ standing seam metal ☐ other
Dormers	3	Number o	of bays — Main facade
□ 0 □ 3 □ shed □ 1 contact □ 4 □ gable □ 2 □ □ □ pediment	© hipped ☐e	D 1 打 2。 取13	□ 4 □ 7 □ 5 □ 8 □ 6 □ □
Porch Stories ☐ yes ☐ no ☐ 1 ☐ : ☐ 2 ☐ .	3 ☐ 1 (center)	Bays	General description Front porch with balustraded upper deck and paired Roman
Building type detached house detached town house row house double house	☐ garage ☐ farmhouse ☐ apartment building ☐ gas station	government commercial (of commercial (st	
Style/period Craftsman/:Colo	onial Revival Date	C /926 Architect/	builder
Location and description of entrance	Central entry with	top- and side-lig	hts.
	symm the	This house feature etrical facade, as upper floor that	ation (plan, exterior and interior decoration, and trim, chimneys, additions, alterations) es projecting eaves, a and a central 3-sided bay on opens out onto the porch deck. ed on a lot that slopes toward
	Sant	calinformation According to the r porn maps, this ho	eal estate records and the use was built ca. 1926.

Source CReal Estate records; Sanborn maps;

8**-**83

Surveyed by Jeff O'Dell, VHLC







3/2/1996



VIRGINIA HISTORIC LANDMARKS COMMISSION

File no. #104 70 Negative no(s). 5124

SURVEY FORM

County/Town/City Albemarke County, Charlottesville
Street address or route number 100 21

Street address or route number 128 Chancellor

USGS Quad Charlottesville Wood, Virginia Original owner

Original use Present owner St. Paul's Memorial Church

Present owner address Present use Contre for Christian Study

Stories 21/2 Foundation and wall const'n

Roof type hip with I dormer

Architect/builder/craftsmen

Date or period c.1925

Source of name

Source of date

State condition of structure and environs apo &

State potential threats to structure Note any archaeological interest

Should be investigated for possible register potential? yes ____ no \(\frac{\frac{1}{2}}{2} \)

Architectural description (Note significant features of plan, structural system and interior and exterior decoration, taking care to point out aspects not visible or clear from photographs. Explain nature and period of all alterations and additions. List any outbuildings and their approximate ages, cemeteries, etc.)

Wood Shingle siding; 21/2 Stories; hip roof with I dormer; 3 bays; single bay I Story porch. Shingle style. c. 1925. Exposed eaves with metal gutter. Second floor porch balustrade. Entrance at centre, side lights and transom. Windows in side bays are 3/1 double sash; occurre second level 3 sided - 4/1 double sash, French door; Dormer - 3 windows, 4/1 double sash. 2 Exterior chimneys. Enclosed porch on back.

Interior inspected? ^o

Historical significance (Chain of title; individuals, families, events, etc., associated with the property.)

Used to be Parish house for St. Paul'D.


Form No. VHLC-01-004

Sources and bibliography
Published sources (Books, articles, etc., with bibliographic data.)

Primary sources (Manuscript documentary or graphic materials; give location.)

Names and addresses of persons interviewed

Plan (Indicate locations of rooms, doorways, windows, alterations, etc.)



Site plan (Locate and identify outbuildings, dependencies and significant topographical features.)



Name, address and title of recorder

7 L. Bosher U. y Da Grad. Student

Date

3-7-80

Page No. 1

City of Charlottesville - Rugby Rd.-University Corner H.D.

DEPARTMENT OF HISTORIC RESOURCE RECONNAISSANCE SURVEY FORM

DHR Idenfication Number: 104-0133-0031

Other DHR Number: 104-70

Property Date(s) 1920s

PROPERTY NAMES

128 Chancellor Street

EXPLANATION

Address-Current

Center for Christian Study

Current

Wood House

Historic

County/Independent City: Charlottesville

State: Virginia

Magisterial District:

Tax Parcel: 9-105-1

USGS Quad Map Name: CHARLOTTESVILLE WEST

UTMs of Boundary:

Center UTM:

Restrict location and UTM data? N

ADDRESSES

Number

Thoroughfare Name

Explanation

128 -

Chancellor Street

Current

Vicinity:

Town/Village/Hamlet: Charlottesville

Name of National Register Historic District:

Rugby Road-University Corner Historic District

Name of DHR Eligible Historic District:

Name of Local Historic District:

Physical Character of General Surroundings: City

Site Description/Notable Landscape Features:

Sloped lot, dropping to rear, with shallow front yard; planted with shrubs

and small to medium-sized deciduous trees.

Ownership: Private

NR Resource Type: Building

WUZITS

Seq. # # of Wuzit Types Historic?

1.0 Single Dwelling Historic

TOTAL:

1

Historic:

1

Non-Historic:

0

PRIMARY RESOURCE EXTERIOR COMPONENT DESCRIPTION

Component	#	Comp Type/Form	Material	Material Treatment
Chimney	2	Exterior end	Brick	Common Bond
Dormer	3	Hip-roofed	Wood	
Foundation	0	Continuous		Plastered
Porch	0	1-story, 2-level	Wood	Colonial Revival
Roof	0	Hipped	Asphalt	Shingle
Walls	0	Frame	Wood	Shingle
Window(s)	0	Sash, double-hung	Wood	8/1
Cornice	0	Open	Wood	Exposed rafter end

INDIVIDUAL RESOURCE INFORMATION

SEQUENCE NUMBER: 1.0 WUZIT: Single Dwelling

Primary Resource? Yes

Estimated Date of Construction: 1920s Source of Date: Site Visit/Written Architectural Style: Bungalow/Craftsman

Description:

Rectangular form, three-bay frame shingled dwelling with Craftsman and Colonial Revival stylistic elements. Front porch, one bay wide, one story with two levels, has paired Doric columns at corners, and wood balustrade on second level; central entrance has three-light sidelights and three-light transom; second-story center bay has bay window with multi-light entrance to upper level of porch in center. Dormers on front, rear, and southwest side are shingled, with three-part double-hung sash windows in each; house roof and dormers have exposed rafter ends. Rear of house has two-level enclosed porch (possibly designed as a sleeping porch) on raised rear basement.

Condition: Good-Excellent

Threats to Resource: None Known

Additions/Alterations Description:

None.

Number of Stories: 2.5

Interior Plan Type:

Accessed? No

Interior Description:

Relationship of Secondary Resources to Property:
None

DHR Historic Context: Domestic

Significance Statement:

Stylistically this house is unusual for its representation of the Craftsman style. It was built as a dwelling, and served in that capacity through 1969; apparently it was after 1983 that it became the Center for Christian Study (Sanborn 1920, 1929, 1941, 1969; O'Dell 1983).

GRAPHIC DOCUMENTATION

Medium	Medium ID #	Frames	Date
B&W 35mm Photos	14643	14 - 15	3/ 2/1996
B&W 35mm Photos	14643	20 -	3/ 2/1996

BIBLIOGRAPHIC DATA

Sequence #: 1.0 Bibliographic Record Type: Survey, Other

Author: O'Dell, Jeffrey M. Citation Abbreviation:

Virginia Historic Landmarks Commission (VHLC) Survey

Notes:

1983. VDHR Archives.

Sequence #: 1.1 Bibliographic Record Type: Map

Author: Sanborn Map Company

Citation Abbreviation:

Sanborn Fire Insurance Maps, Charlottesville, VA

Notes:

1907, 1913, 1920, 1929, 1941, 1969. University of Virginia Alderman Library Government Documents.

CULTURAL RESOURCE MANAGEMENT EVENTS

Date: 3/3/1996

Cultural Resource Management Event: Reconnaissance Survey

Organization or Person: Smead, Susan E.

ID # Associated with Event: CRM Event Notes or Comments:

MAILING ADDRESS

Honorif:
First:
Last:
Suffix:
Title:

Company: University Christian Ministries, Inc.

Address: 1700 University Avenue

City : Charlottesville State: VA

Zip : 22903- Country: USA

Phone/extension:

Individual Category Codes:

Mailing Address Notes:

Surveyor's Notes:

