

VIRGINIA HISTORIC LANDMARKS COMMISSION

File no. Negative no(s). 12:5068

SURVEY FORM

Historic name

County/Town/City AUSEN

Street address or route number USGS Quad HARLOTES

Date or period

Original owner Original use

Present owner Present owner address Source of name Source of date

Present use Acreage

Stories Foundation and wall const'n

Architect/builder/craftsmen

Roof type

State condition of structure and environs

State potential threats to structure Note any archaeological interest

Should be investigated for possible register potential? yes ____ no.

Architectural description (Note significant features of plan, structural system and interior and exterior decoration, taking care to point out aspects not visible or clear from photographs. Explain nature and period of all alterations and additions. List any outbuildings and their approximate ages, cemeteries, etc.)

BRICK (STRETCHER POOND); 1-5TORY; SABALE ROOF, 4 BAYS; 2 BAY ENTRANCE PORCH, VERNALULAR. C. 1965. ENTRANCE IN SECOND BAY FROM LEFT. 6/6 SASH.

Interior inspected?

Historical significance (Chain of title; individuals, families, events, etc., associated with the property.)



Form No. VHLC-01-004

Sources and bibliograph Published sources (Boo	oks, articles, etc., with	bibliographic data.)		
Primary sources (Manuscript documentary or graphic materials; give location.)				
Names and addresses of persons interviewed				
Plan (Indicate location	ns of rooms, doorways,	windows, alterations, etc.)		
Site plan (Locate and	identify outbuildings,	dependencies and significant topog	raphical features.)	+++++++++++++++++++++++++++++++++++++++
Name, address and title of rec	corder	\$ OA	A 0 . 1	Date
Name, address and title of red	DIVID	MVA	APRIL	1100