



VIRGINIA HISTORIC LANDMARKS COMMISSION

File no. 104-72A
Negative no(s). 10 (5074)

SURVEY FORM

Historic name County/Town/City <u>ALBEMARLE/CHARLOTTESVILLE</u> Street address or route number <u>411 ALTAMONT CIRCLE</u> USGS Quad <u>CHARLOTTESVILLE WEST</u> Original owner Original use <u>RESIDENTIAL</u> Present owner Present owner address Present use Acreage	Common name Date or period Architect/builder/craftsmen Source of name Source of date Stories Foundation and wall const'n Roof type
---	---

State condition of structure and environs
GOOD
 State potential threats to structure
 Note any archaeological interest

Should be investigated for possible register potential? yes no

Architectural description (Note significant features of plan, structural system and interior and exterior decoration, taking care to point out aspects not visible or clear from photographs. Explain nature and period of all alterations and additions. List any outbuildings and their approximate ages, cemeteries, etc.)

BRICK (1 1/2 ^{6-course} AMERICAN BOND) AND ^{frame} WOOD. 1 1/2 STORIES. GABLE ROOF, END TO STREET, WITH OPPOSITE DORMERS. 2 BAYS. 1 STORY, 2 BAY HIPPED ROOF PORCH WITH DORIC COLUMNS AND PLASTER RETURNS. ^{Col. Rev. Cottage CA 1920} ~~QUEEN ANNE, CA. 1900.~~ ENTRANCE SOUTH BAY. DOUBLE DOORS, FIXED PANES ABOVE. 1/1 DOUBLE HUNG SASH, DOUBLE SASH IN GABLE END. 2 CENTRAL CHIMNIES. ASBESTOS TILE ROOF. HORIZONTAL WOOD SIDING IN GABLE END.

Interior inspected?
 Historical significance (Chain of title; individuals, families, events, etc., associated with the property.)

