Architectural

Survey

And Historic

TATE TO THE TATE OF THE TATE

Repair and the second second

Identification

 STREET ADDRESS: 405 Third Street NE

 MAP & PARCEL: 33-74

 CENSUS TRACT AND BLOCK: 3-503

 PRESENT ZONING: B-1

 ORIGINAL OWNER: L & S Building Corporation

 ORIGINAL USE: Offices

 PRESENT USE: Offices

 PRESENT OWNER: L & S Building Corporation

 PROBLES: PRESENT OWNER: L & S Building Corporation

 PROBLES: PRESENT OWNER: L & S Building Corporation

HISTORIC NAME :	L & S Building II			
DATE / PERIOD :	1960-61			
STYLE :	No Identifiable Style			
HEIGHT (to cornice) OR STORIES: 2 storeys				
DIMENSIONS AND LA	AND AREA: 49' x 112' (3248 sq. ft.)			
CONDITION :	Good			
SURVEYOR :				
DATE OF SURVEY :	Fall 1980 .			
SOURCES	City Records			
$\mathbb{E}_{\mathcal{T}}_{\mathcal{T}_{\mathcal{T}_{\mathcal{T}_{\mathcal{T}_{\mathcal{T}_{\mathcal{T}}}}}}}}}}$	Historic Landmarks Study			

ARCHITECTURAL DESCRIPTION

This building is two storeys tall and five bays wide. Wall construction is of cinderblock, painted brick red, with the facade brick veneered. There is a moulded brick water table just below the first storey windowsills. A simple entablature on the parapet conceals a flat roof. A six-panel entrance door is recessed within an architrave surround in the center bay. Windows on the facade are double-sash, 9-over-9 light, with wooden sills and architrave trim. They are the same height at both levels and are arranged in vertical bands with white concrete spandrels. A white concrete window-sized panel with brick sill takes the place of the window in the center bay at the second level. Side windows are 6-over-6 light at the first level and 9-over-9 at the second. There is a second entrance in the narrow space between this building and the one facing High Street, and the two buildings are connected by a glass-enclosed bridge at the second level.

HISTORICAL DESCRIPTION

L & S Building Corporation razed the old J. A. G. Davis House on High Street (built c. 1825) and replaced it with two undistinguished office buildings in 1960-61 (City DB 223-32). This building faces on Third Street.

HISTORIC LANDMARKS COMMISSION - DEPARTMENT OF COMMUNITY DEVELOPMENT

C. C	VIRGINIA		File no.
HIST	ORIC LANDMARKS	COMMISSION	Negative no(s). 17:5068
	SURVEY FORM	Commonitor	
Historic name	Common	n name	
County/Town/City	INE THIPD ST	DIT NE	
Street address or route nur		PEET NE	
USGS Quad Original owner	Date or Architec	period t/builder/craftsmen	
Original use	Architec	t/ builder/ craftsmen	
Present owner	Source o	of name	
Present owner address	Source c	of date	45
D	Stories		
Present use Acreage	Foundat	ion and wall const'n	
Horougo	Roof typ	be	
State condition of structur			
		- 3	
State potential threats to s Note any archaeological in			
Note any archaeological in	liciest		
			- X = -
Should be investigated for	possible register potential? yes	no	
	Note significant features of plan, st		
	spects not visible or clear from pho		nd period of all alterations
	tbuildings and their approximate age	s, cemeteries, etc.)	TT Allen
BRICK	(STRETCHER FOO	W); LACK	LES, STEP
ROAF.	5 BANS. CDI	DRIAL RA!	IVAL.
theor ;	J 64.701. COL	Unite . P	N/ HOISED
C. 1965	. ENTRANCE IN	LENIER J	*Y, MOLDED
SURBO	UND 91: CASI	SINSING H	PLAIN
ONERO	und . 16 310	1 WHULDOUS.	1 GALIN
SPANDR	ELS BETWEEN F	IRST AND SA	EOND SLOFY
1101 (DOTA)	S. BLANK WI SDRY,	ATTAIN IN IT	ATT BAN
VINDOW	S. PLANE WI	NAU III LE	JUICE DI-11
SPETAD	DR.		~~~
			â
			9
r.			
Interior inspected? NO.			
Historical significance (Ch	ain of title; individuals, families, eve	nts, etc., associated with th	e property.)
	s		
2			
	3		
		Ϊ:	
y v and		. ⁴	2
	jan and a second se		
			Form No. VHLC-01-004

×49 1008 33-74 215 High 224 3248 L + 8 Blog Corp 1960 built 1960-61 plat 328-537 08223-32+33

DOCKHO 425 # 3rd 345-62 - 2 - storey, 5 - bay CB painted brick red, facade brick veneered (stretchor) flat roof, simple entab on facade moulded brick water table just below window alle windows 9/6 uf wich trim, same ht, wooden alls white conc grandials vertical bands white come window-sized sand of brick sill in center bay at and level cent ent; 6- panel door naised 1 step & set within arch surround connected to other bldg by glass bridge at Ind level another ent on alley bet side windows 6/6 at 1st & 7/6 at 2nd