



VIRGINIA
HISTORIC LANDMARKS COMMISSION
HISTORIC DISTRICT SURVEY FORM

File No. 104-130
Negative no(s). 7221

Street address 422 15th St. NW
Town/City Charlottesville

Historic name

Common name

- Material
- ☒ wood frame (siding: ☐ weatherboard, ☐ shingle, ☐ aluminum, ☐ bricktex, ☐ _____)
 - ☐ brick (bond: ☐ Flemish, ☐ stretcher, ☐ _____-course American, ☐ _____)
 - ☐ stone (☐ random rubble, ☐ random ashlar, ☐ coursed ashlar, ☐ _____)
 - ☐ log (siding: ☐ weatherboard, ☐ shingle, ☐ aluminum, ☐ bricktex, ☐ _____)
 - ☒ stucco
 - ☐ concrete block
 - ☐ enameled steel
 - ☐ other: _____
- ☐ cast iron
☐ terra cotta
☐ glass and metal

Number of Stories	Roof Type	Roof Material
<input type="checkbox"/> 1 <input type="checkbox"/> 2½ <input type="checkbox"/> 1½ <input type="checkbox"/> 3 <input checked="" type="checkbox"/> 2 + attic <input type="checkbox"/> _____	<input type="checkbox"/> shed <input checked="" type="checkbox"/> gable w/ X-gable <input type="checkbox"/> pediment <input type="checkbox"/> hipped <input type="checkbox"/> other: _____	<input type="checkbox"/> slate <input type="checkbox"/> wood shingle <input type="checkbox"/> composition <input checked="" type="checkbox"/> standing seam metal <input type="checkbox"/> other: _____
<p>Dormers</p> <p><input checked="" type="checkbox"/> 0 <input type="checkbox"/> 3 <input type="checkbox"/> shed <input type="checkbox"/> 1 <input type="checkbox"/> 4 <input type="checkbox"/> gable <input type="checkbox"/> 2 <input type="checkbox"/> _____ <input type="checkbox"/> pedimented</p> <p><input type="checkbox"/> hipped <input type="checkbox"/> _____</p>		<p>Number of bays — Main facade</p> <p><input type="checkbox"/> 1 <input type="checkbox"/> 4 <input type="checkbox"/> 7 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 5 <input type="checkbox"/> 8 <input type="checkbox"/> 3 <input type="checkbox"/> 6 <input type="checkbox"/> _____</p>

Porch	Stories	Bays	General description
<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	<input checked="" type="checkbox"/> 1 <input type="checkbox"/> 3 <input type="checkbox"/> 2 <input type="checkbox"/> _____	<input type="checkbox"/> 1 (center) <input type="checkbox"/> 1 (side)	Full-length front porch with tapering wooden columns set on two-foot-high brick piers.
		<input checked="" type="checkbox"/> 2 <input type="checkbox"/> 4 <input type="checkbox"/> 3 <input type="checkbox"/> _____	

Building type

- | | | | |
|--|---|--|-------------------------------------|
| <input checked="" type="checkbox"/> detached house | <input type="checkbox"/> garage | <input type="checkbox"/> government | <input type="checkbox"/> industrial |
| <input type="checkbox"/> detached town house | <input type="checkbox"/> farmhouse | <input type="checkbox"/> commercial (office) | <input type="checkbox"/> school |
| <input type="checkbox"/> row house | <input type="checkbox"/> apartment building | <input type="checkbox"/> commercial (store) | <input type="checkbox"/> church |
| <input type="checkbox"/> double house | <input type="checkbox"/> gas station | <input type="checkbox"/> railroad | <input type="checkbox"/> _____ |

Style/period Decorated Vernacular

Date ca. 1920-20 Architect/builder

Location and description of entrance



Miscellaneous descriptive information (plan, exterior and interior decoration, cornice/eave type, window type and trim, chimneys, additions, alterations)

This house features a cntral cross-gable with polychrome geometric-glazed window. The stucco is painted a light eyellow.

Historical information

The real estate records, which are often inaccurate, claim this house was built in 1920.

Source Real Estate records

Surveyed by Jeff O'Dell, VHLC

Date 8-83