

ROCK HILL: INDEX TO LARGE FORMAT PHOTOGRAPHS

The following information is the same for all photographs:

Property: Rock Hill Landscape, File no. 104-5137

Location: Charlottesville, Virginia

Photographer: Rob Tucher

Date: April 2010

Negative File: Virginia Department of Historic Resources Archives

2801 Kensington Avenue

Richmond, Virginia

PHOTO #	CAPTION
Photo # 1 of 40	VIEW OF ROCK HILL LANDSCAPE IN CONTEXT TAKEN FROM PARK STREET BRIDGE OVER ROUTE 250 BYPASS LOOKING NORTHWEST.
Photo # 2 of 40	GENERAL VIEW OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE IN CONTEXT. TAKEN FROM SOUTH SIDE OF ROUTE 250 BYPASS LOOKING NORTH.
Photo # 3 of 40	VIEW OF ROCK HILL LANDSCAPE SOUTHWEST CORNER AND SECONDARY ENTRANCE. TAKEN FROM SOUTH SIDE OF ROUTE 250 BYPASS LOOKING NORTHEAST.
Photo # 4 of 40	VIEW OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE. TAKEN FROM SOUTH SIDE OF ROUTE 250 BYPASS LOOKING NORTH.
Photo # 5 of 40	CLOSER VIEW OF SOUTHEAST CORNER OF ROCK HILL LANDSCAPE AND EXTERIOR WALL, LOOKING NORTH.
Photo # 6 of 40	CLOSER VIEW OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE FROM NORTH SIDE OF ROUTE 250 LOOKING NORTH.
Photo # 7 of 40	VIEW OF HISTORIC PRIMARY ENTRANCE AND DRIVE TO FORMER ROCK HILL RESIDENCE LOOKING NORTH.
Photo # 8 of 40	SOUTH ELEVATION OF WEST GATEPOST AND DETAIL OF "ROCK HILL" IN STUCCO AT HISTORIC PRIMARY ENTRANCE.
Photo # 9 of 40	NORTH SIDE OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE TAKEN FROM DRIVE LOOKING SOUTH.

Photo # 10 of 40	DETAIL OF CULVERT BENEATH DRIVE NEAR NORTHEAST CORNER OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE. VIEW LOOKING NORTHWEST.
Photo # 11 of 40	NORTH SIDE OF SECONDARY ENTRANCE AND EXTERIOR WALL AT SOUTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING SOUTH.
Photo # 12 of 40	DETAIL OF STONE WALL AND STEPS INTO CIRCULAR PARTERRE AT TOP OF DRIVE. VIEW LOOKING NORTHWEST.
Photo # 13 of 40	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING SOUTH ACROSS CIRCULAR PARTERRE AND DRIVE.
Photo # 14 of 40	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING WEST-SOUTHWEST ACROSS BOXWOOD-LINED DRIVE.
Photo # 15 of 40	VIEW FROM WEST END OF CENTRAL TERRACE LOOKING EAST SOUTHEAST.
Photo # 16 of 40	VIEW FROM WEST END OF CENTRAL TERRACE LOOKING EAST NORTHEAST.
Photo # 17 of 40	DETAIL OF STONE STEPS AT EAST END OF TERRACED LANDSCAPE LOOKING NORTHEAST.
Photo # 18 of 40	VIEW OF SOUTHERN TERRACE FROM WEST END LOOKING NORTHEAST.
Photo # 19 of 40	VIEW FROM CENTRAL TERRACE LOOKING SOUTHWEST TOWARDS ROUTE 250 BYPASS.
Photo # 20 of 40	VIEW FROM SOUTHERN TERRACE LOOKING SOUTHWEST TOWARDS SOUTHWEST CORNER OF ROCK HILL LANDSCAPE AND ROUTE 250 BYPASS.
Photo # 21 of 40	VIEW FROM CENTRAL TERRACE LOOKING NORTHEAST TOWARDS EXTANT BUILDINGS.
Photo # 22 of 40	VIEW FROM NORTHERN TERRACE AND SOUTHEAST CORNER OF EXTANT BUILDINGS LOOKING WEST.
Photo # 23 of 40	DETAIL OF ARCHED SECTION OF EXTERIOR STONE WALL ALONG WEST SIDE OF ROCK HILL LANDSCAPE. VIEW LOOKING NORTHWEST.

Photo # 24 of 40	VIEW OF STONE STEPS ALONG EXTERIOR WALL LEADING FROM FORMAL GARDEN TO NATURALISTIC AREA FILLING NORTHWEST CORNER. TAKEN FROM INSIDE ROCK HILL LANDSCAPE LOOKING SOUTHWEST.
Photo # 25 of 40	VIEW OF EXTERIOR WALL AT WEST SIDE OF PROPERTY. TAKEN FROM INSIDE ROCK HILL LANDSCAPE LOOKING SOUTHWEST.
Photo # 26 of 40	DETAIL OF A STONE-STEPPED SWITCHBACK TRAIL LOCATED IN THE WOODED AREA NEAR NORTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING SOUTHWEST.
Photo # 27 of 40	DETAIL OF A STONE-STEPPED SWITCHBACK TRAIL LOCATED IN THE WOODED AREA NEAR NORTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING NORTHEAST.
Photo # 28 of 40	SOUTHWEST OBLIQUE OF OUTDOOR FIREPLACE LOCATED IN THE WOODED AREA OF ROCK HILL LANDSCAPE, NEAR NORTH EXTERIOR WALL.
Photo # 29 of 40	NORTHWEST CORNER OF EXTERIOR WALL AND ROCK HILL LANDSCAPE. TAKEN FROM SCHENK'S BRANCH LOOKING SOUTH.
Photo # 30 of 40	VIEW FROM SCHENK'S BRANCH WITH ROCK HILL LANDSCAPE AT RIGHT LOOKING NORTHEAST.
Photo # 31 of 40	VIEW FROM OUTDOOR FIREPLACE, LOOKING NORTHWEST THROUGH THE WOODED AREA TOWARDS MCINTIRE PARK.
Photo # 32 of 40	VIEW FROM OUTDOOR FIREPLACE, LOOKING SOUTHWEST THROUGH WOODED AREA TOWARDS ROUTE 250 BYPASS.
Photo # 33 of 40	VIEW OF NORTHWEST CORNER OF ROCK HILL LANDSCAPE, LOOKING NORTH TOWARDS MCINTIRE PARK.
Photo # 34 of 40	WEST ELEVATION OF EXTERIOR WALL NEAR NORTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING NORTHEAST.
Photo # 35 of 40	VIEW OF MCINTIRE PARK FROM ROCK HILL LANDSCAPE, WITH NORTHWEST CORNER OF EXTERIOR WALL IN FOREGROUND, LOOKING NORTHWEST.
Photo # 36 of 40	VIEW FROM A POSITION WEST OF OUTDOOR FIREPLACE, LOOKING NORTH THROUGH WOODED AREA, TOWARDS MCINTIRE PARK.

Photo # 37 of 40	SOUTH ELEVATION OF CIRCA 1930 STONE GARAGE ASSOCIATED WITH FORMER ROCK HILL RESIDENCE.
Photo # 38 of 40	SOUTHWEST ELEVATION OF EXTANT BUILDINGS ASSOCIATED WITH ROCK HILL ACADEMY. VIEW LOOKING NORTHEAST.
Photo # 39 of 40	WEST ELEVATION OF EXTANT BUILDINGS ASSOCIATED WITH ROCK HILL ACADEMY. VIEW LOOKING NORTH.
Photo # 40 of 40	VIEW OF CURRENT ENTRANCE AND DRIVEWAY TO ROCK HILL (MACAA) PROPERTY LOOKING WEST.















BECK HILL

DO NOT ENTER

BECK HILL

ROCK HILL































































