

ROCK HILL: INDEX TO DIGITAL PHOTOGRAPHS

The following information is the same for all photographs:

Property: Rock Hill Landscape, File no. 104-5137

Location: Charlottesville, Virginia

Photographer: Rob Tucher

Date: April 2010

Negative File: Virginia Department of Historic Resources Archives

2801 Kensington Avenue

Richmond, Virginia

PHOTO #	CAPTION
Photo # 1 of 50	VIEW OF ROCK HILL LANDSCAPE IN CONTEXT TAKEN FROM PARK STREET BRIDGE OVER ROUTE 250 BYPASS LOOKING NORTHWEST.
Photo # 2 of 50	GENERAL VIEW OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE IN CONTEXT. TAKEN FROM SOUTH SIDE OF ROUTE 250 BYPASS LOOKING NORTH.
Photo # 3 of 50	VIEW OF ROCK HILL LANDSCAPE SOUTHWEST CORNER AND SECONDARY ENTRANCE. TAKEN FROM SOUTH SIDE OF ROUTE 250 BYPASS LOOKING NORTHEAST.
Photo # 4 of 50	WIDE VIEW OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE. TAKEN FROM SOUTH SIDE OF ROUTE 250 BYPASS LOOKING NORTH.
Photo # 5 of 50	CLOSER VIEW OF SOUTHEAST CORNER OF ROCK HILL LANDSCAPE AND EXTERIOR WALL, LOOKING NORTH.
Photo # 6 of 50	CLOSER VIEW OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE FROM NORTH SIDE OF ROUTE 250 LOOKING NORTH.
Photo # 7 of 50	VIEW OF HISTORIC PRIMARY ENTRANCE AND DRIVE TO FORMER ROCK HILL RESIDENCE LOOKING NORTH.
Photo # 8 of 50	VIEW OF SOUTH ELEVATION OF WEST GATEPOST AND DETAIL OF "ROCK HILL" IN STUCCO AT HISTORIC PRIMARY ENTRANCE.
Photo # 9 of 50	NORTH SIDE OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE TAKEN FROM DRIVE LOOKING SOUTH.

Photo # 10 of 50	DETAIL OF CULVERT BENEATH DRIVE NEAR NORTHEAST CORNER OF HISTORIC PRIMARY ENTRANCE TO FORMER ROCK HILL RESIDENCE. VIEW LOOKING NORTHWEST.
Photo # 11 of 50	NORTH SIDE OF SECONDARY ENTRANCE AND EXTERIOR WALL AT SOUTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING SOUTH.
Photo # 12 of 50	DETAIL OF STONE WALL AND STEPS INTO CIRCULAR PARTERRE AT TOP OF DRIVE. VIEW LOOKING NORTHWEST.
Photo # 13 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING EAST.
Photo # 14 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING SOUTHEAST ALONG CIRCULAR DRIVE.
Photo # 15 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING SOUTH ACROSS CIRCULAR PARTERRE AND DRIVE.
Photo # 16 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING SOUTH.
Photo # 17 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING SOUTHWEST ALONG CIRCULAR DRIVE.
Photo # 18 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING WEST-SOUTHWEST.
Photo # 19 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING WEST.
Photo # 20 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING WEST-NORTHWEST.
Photo # 21 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING NORTHWEST.
Photo # 22 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING NORTHWEST.
Photo # 23 of 50	WIDE VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, LOOKING NORTH-NORTHWEST.
Photo # 24 of 50	360 DEGREE PANORAMIC VIEW TAKEN FROM SITE OF FORMER ROCK HILL RESIDENCE, STITCHED FROM VIEWS IN PHOTOGRAPHS 13–23.

Photo # 25 of 50	VIEW FROM WEST END OF CENTRAL TERRACE LOOKING EAST SOUTHEAST.
Photo # 26 of 50	VIEW FROM WEST END OF CENTRAL TERRACE LOOKING EAST NORTHEAST.
Photo # 27 of 50	DETAIL OF STONE STEPS AT EAST END OF TERRACED LANDSCAPE LOOKING NORTHEAST.
Photo # 28 of 50	VIEW OF SOUTHERN TERRACE FROM NEAR WEST END LOOKING NORTHEAST.
Photo # 29 of 50	VIEW FROM CENTRAL TERRACE LOOKING SOUTHWEST TOWARDS ROUTE 250 BYPASS.
Photo # 30 of 50	VIEW FROM SOUTHERN TERRACE LOOKING SOUTHWEST TOWARDS SOUTHWEST CORNER OF ROCK HILL LANDSCAPE AND ROUTE 250 BYPASS.
Photo # 31 of 50	VIEW FROM CENTRAL TERRACE TOWARDS EXTANT BUILDINGS LOOKING NORTHEAST.
Photo # 32 of 50	VIEW FROM NORTHERN TERRACE AND SOUTHEAST CORNER OF EXTANT BUILDINGS LOOKING WEST.
Photo # 33 of 50	DETAIL OF CIRCULAR PORTAL AND ARCHED SECTION OF EXTERIOR STONE WALL ALONG WEST SIDE OF ROCK HILL LANDSCAPE. VIEW LOOKING NORTHWEST.
Photo # 34 of 50	VIEW OF STONE STEPS LEADING FROM FORMAL GARDEN TO NATURALISTIC AREA FILLING NORTHWEST CORNER. TAKEN FROM INSIDE ROCK HILL LANDSCAPE LOOKING SOUTHWEST.
Photo # 35 of 50	VIEW OF EXTERIOR WALL AT WEST SIDE OF PROPERTY. TAKEN FROM INSIDE ROCK HILL LANDSCAPE LOOKING SOUTHWEST.
Photo # 36 of 50	DETAIL OF A STONE-STEPPED SWITCHBACK TRAIL LOCATED IN THE WOODED AREA AT NORTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING SOUTHWEST.
Photo # 37 of 50	DETAIL OF A STONE-STEPPED SWITCHBACK TRAIL LOCATED IN THE WOODED AREA AT NORTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING NORTHEAST.

Photo # 38 of 50	SOUTHWEST OBLIQUE OF OUTDOOR FIREPLACE LOCATED IN THE WOODED AREA OF ROCK HILL LANDSCAPE, SITUATED NEAR NORTH EXTERIOR WALL.
Photo # 39 of 50	NORTHWEST CORNER OF EXTERIOR WALL AND ROCK HILL LANDSCAPE. TAKEN FROM SCHENK'S BRANCH LOOKING SOUTH.
Photo # 40 of 50	VIEW FROM SCHENK'S BRANCH WITH ROCK HILL LANDSCAPE AT RIGHT LOOKING NORTHEAST.
Photo # 41 of 50	VIEW FROM OUTDOOR FIREPLACE, LOOKING NORTHWEST THROUGH THE WOODED AREA TOWARDS MCINTIRE PARK.
Photo # 42 of 50	VIEW FROM OUTDOOR FIREPLACE, LOOKING SOUTHWEST THROUGH WOODED AREA TOWARDS ROUTE 250 BYPASS.
Photo # 43 of 50	VIEW OF MCINTIRE PARK FROM ROCK HILL LANDSCAPE, WITH NORTHWEST CORNER OF EXTERIOR WALL IN FOREGROUND, LOOKING NORTHWEST.
Photo # 44 of 50	WEST ELEVATION OF EXTERIOR WALL NEAR NORTHWEST CORNER OF ROCK HILL LANDSCAPE. VIEW LOOKING NORTHEAST.
Photo # 45 of 50	VIEW OF NORTHWEST CORNER OF ROCK HILL LANDSCAPE, LOOKING NORTH TOWARDS MCINTIRE PARK.
Photo # 46 of 50	VIEW FROM A POSITION WEST OF OUTDOOR FIREPLACE, LOOKING NORTH THROUGH WOODED AREA, TOWARDS MCINTIRE PARK.
Photo # 47 of 50	SOUTH ELEVATION OF CIRCA 1930 STONE GARAGE ASSOCIATED WITH FORMER ROCK HILL RESIDENCE.
Photo # 48 of 50	SOUTHWEST ELEVATION OF EXTANT BUILDINGS ASSOCIATED WITH ROCK HILL ACADEMY. VIEW LOOKING NORTHEAST.
Photo # 49 of 50	WEST ELEVATION OF EXTANT BUILDINGS ASSOCIATED WITH ROCK HILL ACADEMY. VIEW LOOKING NORTH.
Photo # 50 of 50	VIEW OF CURRENT ENTRANCE AND DRIVEWAY TO PROPERTY LOOKING WEST.

PLEASE NOTE: A set of eighty six (86) supplemental color digital images, including photographs captured in April 2010 and in January, February, and June, 2011, have also been compiled and are submitted as part of the documentation packet for the Rock Hill Landscape property (VA DHR ID: 104-5137).







SPEED
LIMIT
35







Historic
Blount County

DO NOT ENTER



DO NOT ENTER



ROCK HILL















































































LUNCH ROOM





