Property Names Name Explanation Function/Location	Name	Property Evaluation Status	
	House, 820 Page Street		
Property Addresses			
Current - 820 Page Street			
County/Independent City(s):	Charlottesville (Ind. City)		
Incorporated Town(s):	No Data		
Zip Code(s):	22903		
Magisterial District(s):	No Data		
Tax Parcel(s):	No Data		
USGS Quad(s):	CHARLOTTESVILLE EAST		

Additional Property In	formation	
Architecture Setting:	Urban	
Acreage:	No Data	
Site Description:		
northeast property line is be metal railing near the cente	ry house is located on the south side of Page Street, about halfway between 8th and 9th Streets NW. The ordered by box hedges. The property is sited lower than street level and accessed by descending steps with a r. A rounded bush is located along the southeast elevation. The shed is located to the south of the house's consists of a house and a shed.	
Surveyor Assessment:		
Viewer 2020). This is conf front porch and a partial-wi Sanborn Map Company). E rear porch was enclosed an	to the Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS irmed by the 1929 Sanborn Maps, which depict a one-story rectangular house with an almost full-width idth rear porch at the west corner. The footprint remains unchanged in 1950 (Sanborn Map Company 1929; by 1968, a rear cross gable addition was constructed on the southeast half of the southwest elevation and the d connected to this addition under a shed roof (NETR 1968). The shed was built by 1994 (NETR 1994). For several decades by Charles Allen (Hill Directory Co. 1931; Hill Directory Co. 1940; Hill Directory Co.	
house to the east between 1 slightly compromised by re	integrity of location. The integrity of setting is slightly compromised by the demolition of the neighboring 994 and 2002 (NETR 1994; NETR 2002). The integrity of design, materials, and workmanship have been placement roofing (from standing seam metal to asphalt shingles). The property retains good integrity of erall, this property retains good integrity.	
This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.		
Surveyor Recommendation:	Recommended Not Eligible	
Ownership		
<b>Ownership Category</b>	Ownership Entity	

**Ownership Category** Private **Ownership Entity** No Data

Primary Resource Information

<b>Resource Category:</b>	Domestic
<b>Resource Type:</b>	Single Dwelling
NR Resource Type:	Building
Date of Construction:	1925
Date Source:	Local Records
Historic Time Period:	World War I to World War II (1917 - 1945)
Historic Context(s):	Domestic
Other ID Number:	No Data

# Virginia Department of Historic Resources Architectural Survey Form

DHR ID: 104-0240 Other DHR ID: No Data

Architectural Style:	Vernacular	
Form:	No Data	
Number of Stories:	1.0	
Condition:	Good	
Threats to Resource:	None Known	

### **Architectural Description:**

Architecture Summary: Single dwelling located in the Chip Housing Rehab Project.

February 1991

January 2020: This one-story house sits on a stuccoed, concrete block foundation; is clad in stucco; and has a side-gabled roof that is covered in asphalt shingles. There is an interior concrete chimney on the ridgeline in the east end. The northeast-facing facade features a one-story, almost full-width, shed roof porch covered with standing seam metal and supported by square concrete block columns with concrete block knee walls. The main entrance for this house is west of center. There is a front-gabled, partial-width addition on the east half of the southwest (rear) elevation, thereby creating a cross-gabled roof. The west half of the southwest elevation has a shorter, partial-width wing with a shed roof. This smaller wing's roof is partially clad in asphalt shingles and partially clad in standing seam metal (USGS 2016). There is a secondary entrance on the northwest elevation of this smaller wing. Visible fenestration includes two-over-two and six-over-six, double-hung, wood windows, some with metal storm windows; single-leaf wood doors with a metal storm door.

### **Exterior Components**

<b>Component</b> Porch Chimneys Roof	<b>Component Type</b> 1-story, 3-bay Interior Gable	<b>Material</b> Stucco Concrete Asphalt	<b>Material Treatment</b> Square Stuccoed/Parged Shingle
Windows Structural System and Exterior Treatment	Sash, Double-Hung Not Visible	Wood Unknown	1/1 Stuccoed
Roof	Shed	No Data	Other

# **Secondary Resource Information**

# Secondary Resource #1

<b>Resource Category:</b>	Domestic
Resource Type:	Shed
NR Resource Type:	Building
Date of Construction:	ca 1994
Date Source:	Map
Historic Time Period:	Post Cold War (1992 - Present)
Historic Context(s):	Domestic
Other ID Number:	No Data
Architectural Style:	No discernible style
Form:	No Data
Number of Stories:	1.0
Condition:	Poor
Threats to Resource:	Neglect
Anabitantunal Decemintion	

**Architectural Description:** 

January 2020: There is a one-story shed to the south of the house. This shed is clad in paneled plywood and has a shed roof that is covered in asphalt shingles. Visible fenestration includes a small vented opening.

# **Exterior Components**

Component	<b>Component Type</b>	<b>Material</b>	<b>Material Treatment</b>
Structural System and	Wood Frame	Plywood/Particle Board	Panels
Exterior Treatment Roof	Shed	Asphalt	No Data

Historic District Informa	ation		
Historic District Name:	No Data		
Max 21, 2020		1	Daga, 2 of 2

Local Historic District Name:	No Data
Historic District Significance:	No Data

# **CRM Events**

# Event Type: Survey: Phase I/Reconnaissance

<b>Project Review File Number:</b>	No Data
Investigator:	Erin Que
Organization/Company:	The 106 Group Ltd.
Photographic Media:	Digital
Survey Date:	2/5/2020
Dhr Library Report Number:	No Data

### **Project Staff/Notes:**

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer 2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

# National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

## Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1920, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

### United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Event Type: Survey:Windshield**

Project Review File Number:	No Data
Investigator:	No Data
Organization/Company:	Unknown (DSS)
Photographic Media:	No Data
Survey Date:	2/1/1991
Dhr Library Report Number:	No Data
Project Staff/Notes:	
No Data	

# **Bibliographic Information**

### **Bibliography:**

No Data

### **Property Notes:**

No Data

