| Property Names Name Explanation Function/Location | Name House, 204 10th Street NW | Property Evaluation Status | |
|---|-----------------------------------|----------------------------|--|
| Property Addresses | | | |
| Current - 204 10th Street NV | W | | |
| County/Independent City(s): | Charlottesville (Ind. City) | | |
| Incorporated Town(s): | No Data | | |
| Zip Code(s): | 22903 | | |
| Magisterial District(s): | No Data | | |
| Tax Parcel(s): | No Data | | |
| USGS Quad(s): | CHARLOTTESVILLE EAST | | |

| Additional Property Info | rmation |
|---|---|
| Architecture Setting: | Urban |
| Acreage: | No Data |
| Site Description: | |
| a concrete retaining wall alon properties, while the southeas | a-half-story dwelling is located on the east side of 10th Street NW. The northwest side of the property has ng the street. The front yard has a short metal fence. The northwest property line is bordered by residential st is bordered by commercial properties. The rear (east) property line abuts the Westhaven community The property consists of a house. |
| Surveyor Assessment: | |
| by Irene Buford Burton, and l a prominent family in Charlo when it opened in 1966 (Cvil rear (Sanborn Map Company remained largely unchanged housed Cox's Row, a line of | was built in 1920 according to the City of Charlottesville Property Records. This house is currently owned has been since 1971 (City of Charlottesville GIS Viewer 2020). Irene may be related to the Buford family, ttesville, starting with Florence Buford, a famous teacher for whom Buford Middle School was named lepedia 2019). This house first appears on the 1929 Sanborn Map, with a large accessory dwelling in the '1929). It appears the same in the 1950 Sanborn Map (Sanborn Map Company 1950). This house has over time, though its surroundings have altered considerably. Holly Drive, to the east of the house, once row houses built circa 1920 to house railroad workers. Defined as blighted, they were demolished for the n 1963 (Department of Community Development 1990:6). |
| Housing Project (Department | tegrity of location and setting, impacted by the loss of Cox's Row and the construction of the Westhaven t of Community Development 1990:6). The integrity of design, materials, and workmanship have been placement windows. This property retains excellent integrity of feeling and association. Overall, this y. |
| is located in the potential 10th study is recommended to dete areas of Ethnic Heritage, Con | ed as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it h & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further ermine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the nmunity Planning and Development, and Social History, and under Criterion C in the area of ncludes one contributing primary resource. |
| Surveyor Recommendation: | Recommended Not Eligible |
| Ownership | |
| Ownership Category Private | Ownership Entity No Data |

Primary Resource Information

| Resource Category: | Domestic |
|---------------------------|---|
| Resource Type: | Single Dwelling |
| NR Resource Type: | Building |
| Date of Construction: | 1920 |
| Date Source: | Local Records |
| Historic Time Period: | World War I to World War II (1917 - 1945) |
| Historic Context(s): | Domestic |

Virginia Department of Historic Resources

Architectural Survey Form

| Other ID Number: | No Data |
|----------------------|------------|
| Architectural Style: | Vernacular |
| Form: | No Data |
| Number of Stories: | 2.5 |
| Condition: | Good |
| Threats to Resource: | None Known |
| | |

Architectural Description:

January 2020: This two-and-a-half-story house is clad in red stretcher-bond brick and has a hipped roof covered with asphalt shingles. There is a brick chimney on the north and south roof slopes. On the northwest-facing facade, there is a one-story, almost full-width, open porch with a hipped roof. It has a wood floor and wood Doric columns. The porch is accessed by concrete steps in the north end and has a wood railing in the south half. Also, on the front facade, there is a front gable roof dormer that is clad in square aluminum shingles. The fenestration openings are slightly arched. There is a one-story wing on the southeast elevation. Visible fenestration consists of one-over-one, double-hung vinyl windows; and a single-leaf wood door with a metal and glass storm door.

Exterior Components

| Component | Component Type | Material Brick | Material Treatment |
|---|--------------------|--------------------------|----------------------|
| Chimneys | Interior Slope | | Strecther Bond |
| Dormer | Gable | Aluminum | No Data |
| Foundation | Solid/Continuous | Concrete | Uncoursed |
| Porch | 1-Story Full-Width | Wood | Doric |
| Structural System and Exterior Treatment | Masonry | Brick | American/Common Bond |
| Windows | Double-hung | Vinyl | No Data |
| Roof | Hipped | Asphalt | No Data |

Secondary Resource Information

| Historic District Information | 1 |
|---------------------------------|---------|
| Historic District Name: | No Data |
| Local Historic District Name: | No Data |
| Historic District Significance: | No Data |

CRM Events

Event Type: Survey: Phase I/Reconnaissance

| Project Review File Number: | No Data |
|-----------------------------|--------------------|
| Investigator: | Erin Que |
| Organization/Company: | The 106 Group Ltd. |
| Photographic Media: | Digital |
| Survey Date: | 2/5/2020 |
| Dhr Library Report Number: | No Data |

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer 2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Virginia Department of Historic Resources

Architectural Survey Form

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

Cvillepedia 2019 Florence Buford. Electronic document, https://www.cvillepedia.org/Florence_Buford, accessed February 22, 2020.

Department of Community Development 1990 From Porch Swings to Patios: An Oral History of Charlottesville Neighborhoods, 1914-1984. City of Charlottesville, Charlottesville, Virginia.

Property Notes:

No Data

