Architectural Survey Form

DHR ID: 104-5638 Other DHR ID: No Data

# **Property Information**

**Property Names** 

Name Explanation Name

Duplex, 332-334 10th Street NW Function/Location

**Property Addresses** 

Current - 332-334 10th Street NW

County/Independent City(s): Charlottesville (Ind. City)

**Incorporated Town(s):** No Data **Zip Code(s):** 22903 **Magisterial District(s):** No Data Tax Parcel(s): No Data

USGS Quad(s): CHARLOTTESVILLE EAST

# **Additional Property Information**

**Architecture Setting:** Urban Acreage: No Data

**Site Description:** 

January 2020: This two-story duplex is located on the east side of 10th Street NW. The site slopes downhill to the southeast. There is a gravel driveway to the southeast of the property that leads to a parking lot shared with the adjacent property to the southwest and the other two buildings on this lot.

**Property Evaluation Status** 

#### Surveyor Assessment:

January 2020: According to City of Charlottesville Property Records, this duplex was built in 1940 (City of Charlottesville GIS Viewer 2020). This building first appears on the 1950 Sanborn Map, along with the other two properties on the lot, and has the same footprint as it does today (Sanborn Map Company 1950; USGS 2017)

This property retains excellent integrity of location and setting. The integrity of design, material, and workmanship have been mildly compromised through exterior material changes. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

**Surveyor Recommendation:** Recommended Not Eligible

Ownership

**Ownership Category Ownership Entity** 

Private

## **Primary Resource Information**

**Resource Category:** Domestic Resource Type: Double/Duplex NR Resource Type: Building 1940 **Date of Construction:** 

**Date Source:** Local Records

World War I to World War II (1917 - 1945) **Historic Time Period:** 

Good

**Historic Context(s):** Domestic Other ID Number: No Data **Architectural Style:** Vernacular Form: Rectangular **Number of Stories:** 2.0 **Condition:** 

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5638

Threats to Resource: None Known

## **Architectural Description:**

January 2020: This two-story duplex rests on a concrete foundation, is clad in vinyl siding, and has a hipped roof covered in standing seam metal. There are three interior brick chimneys: one on the southeast roof slope, one on the southwest roof slope, and one on the northwest roof slope. The front (northwest) facade features two one-story porticos with hipped roofs, one on either end of the facade. These are supported by turned wood columns, and the southernmost porch has a turned wood railing. Both porches are accessed via concrete stairs. There are two entrances on this facade, each covered by a porch. Visible fenestration includes six-over-six, double-hung, vinyl windows; and 15-light singleleaf, wood doors.

## **Exterior Components**

Component Material **Material Treatment** Component Type Chimnevs Interior Slope Brick Strecther Bond Foundation Solid/Continuous Concrete Uncoursed Porch Portico/Entry Porch Wood Turned Structural System and Wood Frame Vinyl Siding **Exterior Treatment** 

No Data Vinyl Double-hung Windows Roof No Data Hipped Metal

## **Secondary Resource Information**

#### **Historic District Information**

**Historic District Name:** No Data **Local Historic District Name:** No Data **Historic District Significance:** No Data

## **CRM Events**

# Event Type: Survey:Phase I/Reconnaissance

**Project Review File Number:** No Data Investigator: Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville,

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

May 21, 2020 Page: 2 of 3 Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5638

United States Geological Survey [USGS]
1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Bibliographic Information**

# **Bibliography:**

No Data

## **Property Notes:**

January 2020: This building is one of three on the lot, though this is the oldest one of the three (City of Charlottesville GIS Viewer 2020). However, for the purpose of this survey, we have separated this building from the other two since it has always had a separate address.

May 21, 2020 Page: 3 of 3

