Architectural Survey Form

DHR ID: 104-5644 Other DHR ID: No Data

### **Property Information**

**Property Names** 

Name Explanation Name

Function/Location Duplex, 344A&B 10th Street NW

Property Addresses

Current - 344 10th Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

**Property Evaluation Status** 

## **Additional Property Information**

Architecture Setting: Urban
Acreage: No Data

**Site Description:** 

January 2020: This two-story house is located on the east side of 10th Street NW. There is a large parking lot at the rear of the property, shared with the adjacent building to the southeast, that is accessed through a driveway on the northwest side of the lot. There are large trees to the rear of the property, as well as one in the southwest corner. This property consists of a house and shed.

#### **Surveyor Assessment:**

January 2020: According to the City of Charlottesville Property Records, this building was built in 1925 (City of Charlottesville GIS Viewer 2020). However, it does not appear on the 1929 Sanborn Map, and does not appear until the 1950 Sanborn Map (Sanborn Map Company 1929; Sanborn Map Company 1950). Therefore, it is likely the building was not actually constructed until closer to 1930. The shed to the northeast corner of the property was constructed around 2010, according to aerial photographs (USGS 2009; USGS 2011).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship have been mildly compromised through exterior material changes. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

# **Primary Resource Information**

Resource Category:DomesticResource Type:Double/DuplexNR Resource Type:BuildingDate of Construction:ca 1930Date Source:Map

**Historic Time Period:** World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

# **Architectural Description:**

January 2020: This two-story duplex sits on a concrete foundation, is clad in aluminum siding, and has a cross-gabled roof that is covered in standing seam metal. There are three interior brick chimneys on this house: One on the northeast roof slope near the ridgeline, one on the northeast roof slope near the rear of the building, and one on the southwest roof slope near the rear of the building. The front (northwest) facade features a full-width, one-story, open porch with a hipped roof covered in asphalt shingles. The porch roof is supported by square wood columns, and the porch has wood railings, and is accessed by concrete steps with wood railings. The underside of the porch is covered by wood latticework. The southeast (rear) elevation includes a two-story, partial-width, shed-roof wing. Visible fenestration includes six-over-six, double-hung, vinyl windows, some with metal screens; six-over-one, double-hung, vinyl windows; six-over-six metal windows; and nine-light, single-leaf wood doors with transoms and metal and glass storm doors.

#### **Exterior Components**

ComponentComponent TypeMaterialMaterial TreatmentChimneysInterior SlopeBrickAmerican/Common BondFoundationSolid/ContinuousConcreteUncoursed

Porch Structural System and Exterior Treatment Solid/Continuous Concrete
1-Story Full-Width Wood
Wood Frame Aluminum

Uncour Posts m Siding

Windows Double-hung
Roof Cross Gable

Metal Metal No Data No Data DHR ID: 104-5644

# **Secondary Resource Information**

# Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 2010Date Source:Map

**Historic Time Period:** Post Cold War (1992 - Present)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Excellent
Threats to Resource: None Known

# **Architectural Description:**

January 2020: There is a one-story shed located to the east of the duplex. This shed sits on a wood panel foundation, is clad in vertical wood siding, and has a gambrel roof covered in asphalt shingles. Visible fenestration includes vertical wood swing doors.

# **Exterior Components**

Component Component Type Material **Material Treatment** Not Visible Foundation Piers Wood Wood Frame Vertical Board Structural System and Wood **Exterior Treatment** No Data Roof Gambrel Asphalt

## **Historic District Information**

Historic District Name:No DataLocal Historic District Name:No DataHistoric District Significance:No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form

DHR ID: 104-5644 Other DHR ID: No Data

#### **CRM Events**

# **Event Type: Survey:Phase I/Reconnaissance**

**Project Review File Number:** No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

#### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Bibliographic Information**

### **Bibliography:**

No Data

#### **Property Notes:**

No Data

Page: 3 of 3 May 21, 2020

