Architectural Survey Form Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

House, 319 10 1/2 Street NW Function/Location

Property Evaluation Status

DHR ID: 104-5665

Property Addresses

Current - 319 10 1/2 Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s): No Data 22903 **Zip Code(s): Magisterial District(s):** No Data Tax Parcel(s): No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban Acreage: No Data

Site Description:

2016: This property was surveyed in 2012-2016 by City of Charlottesville Neighborhood Development Services. The paved driveway in the side yard leads to a one-bay, gable roof, open-air carport/garage which was built in 1960. Several large hedge plantings are located around the porch and around the concrete block wall which separates the front yard from the sidewalk. A concrete path leads from the sidewalk up to the central entrance.

Surveyor Assessment:

2016: Ownership History

G. M. McNutt, trustee sold the property to Barley Clark on April 2, 1918(City 31 – 319). Barley Clark died on Sept 25, 1926.All five Children of Barley Clark and their spouses (Gertrude Clark Cooper and husband Edward; Mary Clark Cooper and her husband Dewey; Violet Clark Lewis and her husband William; William Clark (separated); George Clark (single)) willed the property to Bertie Clark (Barley's widow, and their mother) on July 23, 1929(City 66 – 74). The Clark family continued to own the home, exchanging between siblings through the 1970s.

From 1919 when the house was built until his death in 1926, African American chauffer Barley Clark lived in the home with his wife Bertie Clark. After his death, Bertie Clark continued to own the home until her death in 1956. Daughter Mary E. Williams, a widow, took over the property and ran a beauty shop from 1956 through the 1960s. She remarried in 1960 to Hubert Stanley, an African American chauffer, changing her name to Mary Williams Stanley.

Statement of Significance

This house was in the Clark/Williams/Stanley family for over fifty years. The house was used as a business, a beauty shop, in addition to being a residence. Most of the original materials have been replaced in the dwelling, but it has social and community value.

2020: This property is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category **Ownership Entity**

Private No Data

Primary Resource Information

Resource Category: Domestic Resource Type: Single Dwelling NR Resource Type: Building **Date of Construction:** ca 1919 Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

May 21, 2020 Page: 1 of 3 Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5665

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

2016: This three-bay, one-story, symmetrical frame and stucco dwelling house was built around 1919. The house had several rehabilitations in 1954, 1976, and 1982. Originally a cross-gable, T-shaped house, the T was filled into a square with a pair of shed roof additions (one on either side of the T) in 1960. The multi-gable roof has asphalt shingles and rectangular louvered vents in each gable pediment. There is a three-bay porch with a hipped asphalt shingle roof, rectangular stuccoed posts and a parged concrete foundation. Front facing windows appear to be 1/1 vinyl sash.

Exterior Components

Component Component Type Material Material Treatment
Structural System and Exterior Treatment

Collagor Control Front Collagor Co

Gable w/Central Front Gable No Data Roof Asphalt Windows Double-hung Vinyl No Data Interior Central Strecther Bond Chimneys Brick 1-Story Full-Width Porch Stucco Square

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:CarportNR Resource Type:StructureDate of Construction:1960

Date Source: Local Records

Historic Time Period: The New Dominion (1946 - 1991)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: No Data
Condition: Good
Threats to Resource: None Known

Architectural Description:

2016: The paved driveway in the side yard leads to a one-bay, gable roof, open-air carport/garage which was built in 1960.

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5665

Project Review File Number: No Data Investigator: Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital **Survey Date:** 2/5/2020 No Data **Dhr Library Report Number:**

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

1931, 1940, Í950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

