Architectural Survey Form

DHR ID: 104-5699 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location

House, 615 10 1/2 Street NW

Property Addresses

Current - 615 10 1/2 Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s): No Data 22903 **Zip Code(s): Magisterial District(s):** No Data Tax Parcel(s): No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban Acreage: No Data

Site Description:

January 2020: This two-story house is located on the west side of 10 1/2 Street NW, on the corner of 10 1/2 Street NW and Rosser Avenue. The property is surrounded by fencing of various types. There are large trees of varying types to the northeast and southwest of the property. This property consists of a house and a shed in the rear.

Property Evaluation Status

Surveyor Assessment:

January 2020: This dwelling was built in 1920 on Lot 1 of the John West Lots, purchased by John West in 1885 according to City of Charlottesville Property Records (City of Charlottesville GIS Viewer 2020). This lot was first owned by Norman Dennis, who bought it from John West around 1917 (ACHS n.d.). The house first appears on the 1920 Sanborn Map, with an open, one-story, full-width porch on the southern elevation from the extending wing (Sanborn Map Company 1920). This porch was enclosed by 1929, and the house's footprint has remained the same since then, according to Sanborn Maps, but with a different secondary building (Sanborn Map Company 1929). This secondary building was still extant in 1950 but was replaced in 2008 with the current shed (Sanborn Map Company 1950; USGS 2008).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship has been minorly compromised through replacement windows. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category **Ownership Entity**

Primary Resource Information

Resource Category: Domestic Single Dwelling Resource Type: NR Resource Type: Building **Date of Construction:** 1920

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic Other ID Number: No Data **Architectural Style:** Italianate

May 21, 2020 Page: 1 of 3 Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5699

Form: L-Plan
Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: The house rests on a stuccoed foundation, is clad in stucco, and has a cross-gabled roof covered in standing seam metal roofing. The southwest (front) façade features a partial-width, one-story open porch with a shed roof. The porch roof is supported by square wood columns with decorative scrollwork brackets, and the porch is accessed via concrete steps. All of the windows on this facade have fixed wood shutters. The main entrance is in the center of the facade, below the front gable. There are two interior stuccoed chimneys on either side of the center ridge. There is a one-story wing to the northwest of the property. This wing is clad in stucco and has a front gable roof that extends into a shed roof towards the southeast covered in standing seam metal roofing. Visible fenestration includes one-over-one, double-hung, metal windows; one-over-one, double hung, vinyl windows; and a single-leaf wood door with a transom and two sidelights; and a metal storm door.

Exterior Components

Component Component Type Material Material Treatment Chimneys Interior Central Stuccoed/Parged Unknown 1-Story Partial Width Porch Wood Square Wood Frame Structural System and Unknown Stuccoed Exterior Treatment Windows Double-hung Vinyl No Data Roof Gable w/Central Front Gable Metal No Data

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 2008Date Source:Map

Historic Time Period: Post Cold War (1992 - Present)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Excellent
Threats to Resource: None Known

Architectural Description:

January 2020: There is a shed to the southeast of this house. This shed is clad in vertical wood siding and has a shed roof covered in corrugated metal roofing. Visible fenestration includes a single-leaf wood door; and a fixed four-light vinyl window.

Exterior Components

ComponentComponent TypeMaterialMaterial TreatmentFoundationPiersWoodNo DataStructural System and
Exterior TreatmentWood FrameWoodVertical Board

WindowsFixedVinylNo DataRoofShedMetalNo Data

Historic District Information

Historic District Name:No DataLocal Historic District Name:No DataHistoric District Significance:No Data

May 21, 2020 Page: 2 of 3

DHR ID: 104-5699 Other DHR ID: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

Albemarle-Charlottesville Historical Society [ACHS] n.d. John West Lots of 10 ½ Street. On file at the Albemarle-Charlottesville Historical Society, Charlottesville, Virginia.

Property Notes:

No Data

May 21, 2020 Page: 3 of 3

