Architectural Survey Form

Other DHR ID: No Data

DHR ID: 104-5718

Property Information

Property Names

Name Explanation Name

Function/Location House, 423 11th Street NW

Property Evaluation Status

Property Addresses

Current - 423 11th Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

2016: This property was surveyed in 2012-2016 by City of Charlottesville Neighborhood Development Services. The front yard and sidewalk are separated by a privet hedge and a brick walkway leading from the sidewalk to the front door. A two-stall garage with gable roof and vinyl siding is sited at the end of an unpaved driveway at the side of the house.

Surveyor Assessment:

2016: Ownership History

James Tyler purchased the property on July 15, 1911 from C.C. Cocke (County 97-346) who had bought it from the Charlottesville Land Company in 1891 (County 96 – 330). The Tyler family owned the land until 1964 when it was purchased by Silas and Beatrice Walker (City 256-331). The Walkers owned the home through the 1970s.

Social History

The African American family of James Tyler and Ada Tyler owned and resided in the home from 1912 until 1964. James Tyler worked as a driver and later, his oldest son worked as a miller at Lovegrove Milling Company to support the family.

Statement of Significance

Built for the family of James and Ada Tyler, the house is well-preserved with original windows and a large set back from the road, giving the property a distinctly rural feel. The Tyler family owned and lived in the house for over fifty years, giving it further social and community value.

2020: This property is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:ca 1911Date Source:Local Records

Historic Time Period: Reconstruction and Growth (1866 - 1916)

Historic Context(s): Domestic
Other ID Number: No Data

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5718

Architectural Style: Vernacular
Form: No Data
Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

2016: This two-bay, two-story, frame and stucco house was built around 1911. The first major rehabilitation took place in 1956. Originally L-shaped, a two-story one-bay hipped roof addition made the footprint into a square. The current dwelling has a cross-gable roof with asphalt shingles and an interior plaster- coated brick chimney. The original 6/6 wood sash windows remain in place. Across the façade is a two-bay hipped roof porch with rectangular wood post on brick piers, and stucco coated triangular brackets.

Exterior Components

Exterior Treatment

Cross Gable No Data Asphalt Roof Stuccoed/Parged Chimneys Interior End Brick Windows Double-hung Wood No Data 1-Story Full-Width Porch Stucco Square

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:GarageNR Resource Type:BuildingDate of Construction:ca 1968Date Source:Map

Historic Time Period: The New Dominion (1946 - 1991)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Fair
Threats to Resource: None Known

Architectural Description:

2016: A two-stall garage with gable roof and standing seam metal siding is sited at the end of an unpaved driveway at the side of the house

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number:No DataInvestigator:Erin Que

Organization/Company: The 106 Group Ltd.

May 21, 2020 Page: 2 of 3

DHR ID: 104-5718

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

