Architectural Survey Form

DHR ID: 104-5730 Other DHR ID: No Data

# **Property Information**

**Property Names** 

Name Explanation Name

Function/Location House, 502 12th Street NW

**Property Evaluation Status** 

**Property Addresses** 

Current - 502 12th Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

# **Additional Property Information**

Architecture Setting: Urban
Acreage: No Data

**Site Description:** 

January 2020: This one-story house is significantly set back from the east side of 12th Street NW and faces Gordon Avenue, from which it is also significantly set back due to the adjacent lot. There is a large tree in the northwest end of the lot, which is bordered by a chain link fence. The northeast property line has a few bushes. A gravel sidewalk extends from the 12th Street NW sidewalk towards the house. There are also two trees in front of the house and a shed adjacent to the southeast elevation. The southeast property line features box hedges. This property consists of a house and a shed.

### Surveyor Assessment:

January 2020: According to the Charlottesville City Property Records, this house was constructed in 1920 (City of Charlottesville GIS Viewer 2020). However, it is not depicted on the 1920, 1929, or 1950 Sanborn Maps (Sanborn Map Company 1920; Sanborn Map Company 1929; Sanborn Map Company 1950). Additionally, there is no listing for 502 12th Street NW in the 1959 city directory (Hill Directory Co. 1959). The house is visible in a 1963 aerial photograph (NETR 1963). The shed was built c. 2018 (City of Charlottesville GIS Viewer 2020).

This property retains good integrity of location and setting, minorly impacted by the construction of the shed. The integrity of design, materials, and workmanship have been slightly compromised by replacement windows. The property retains good integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

vate No Do

## **Primary Resource Information**

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:ca 1963Date Source:Map

**Historic Time Period:** The New Dominion (1946 - 1991)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5730

Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

#### **Architectural Description:**

January 2020: This one-story house rests on a concrete foundation, is clad in stucco, and has an asymmetrical side gable roof that is covered with asphalt shingles. On the southwest-facing facade there is a partial-width, one-story, open porch. It has square wood posts, wood knee walls, and a shed roof covered with asphalt shingles. There is a partial-width, one-story wing on the northwest elevation, which gives the house a slight L-shape. This wing has a small entry porch on the southwest façade, with the same treatment as the main porch except that this entry porch has a front gable roof. There is a shorter exterior stretcher bond brick chimney in the center of the northwest elevation, where the wing meets the main block of the house. There is a taller interior stretcher bond brick chimney on the ridgeline. Visible fenestration consists of six-over-six, double-hung, vinyl windows; a multi-pane stained glass window; and single-leaf wood doors with wood screen doors.

#### **Exterior Components**

Component Component Type Material Material Treatment Strecther Bond Chimneys Interior Central Brick Foundation Solid/Continuous Concrete Stuccoed/Parged 1-Story Partial Width Porch Wood Posts Structural System and Not Visible Unknown Stuccoed **Exterior Treatment** Windows Double-hung Vinyl No Data Roof Side Gable Asphalt No Data

#### **Secondary Resource Information**

### Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 2018Date Source:Map

**Historic Time Period:** Post Cold War (1992 - Present)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Excellent
Threats to Resource: None Known

#### **Architectural Description:**

January 2020: There is a one-story shed adjacent to the southeast elevation of the house. It rests on wood posts in ground covered by wood latticework, is clad in wood siding, and has a cross gable roof covered with asphalt shingles. There is a partial-width, open porch on the west corner of the structure. The porch has a wood column with an entranceway at the southeast end. Visible fenestration consists of a six-over-six, double-hung, vinyl window; a single-leaf wood door with nine lights, and leaded wood awning windows.

#### **Exterior Components**

Component Component Type Material **Material Treatment** Post-in-ground 1-Story Partial Width Foundation Wood Porch Wood Turned Structural System and Wood Frame Siding Exterior Treatment Double-hung Vinyl No Data Windows Cross Gable Asphalt No Data

## **Historic District Information**

Historic District Name: No Data
Local Historic District Name: No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5730

**Historic District Significance:** No Data

## **CRM Events**

## Event Type: Survey:Phase I/Reconnaissance

**Project Review File Number:** Investigator: Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

## **Bibliographic Information**

### Bibliography:

No Data

### **Property Notes:**

No Data

Page: 3 of 3 May 21, 2020

