| D. A.N.   |                                  |                            |  |
|---|----------------------------------|----------------------------|--|
| Property Names<br>Name Explanation<br>Function/Location | Name<br>House, 314 8th Street NW | Property Evaluation Status |  |
| Property Addresses                                      |                                  |                            |  |
| Current - 314 8th Street NW                             |                                  |                            |  |
| County/Independent City(s):                             | Charlottesville (Ind. City)      |                            |  |
| Incorporated Town(s):                                   | No Data                          |                            |  |
| Zip Code(s):  | 22903                            |                            |  |
| Magisterial District(s):                                | No Data                          |                            |  |
| Tax Parcel(s):  | No Data                          |                            |  |
| USGS Quad(s):   | CHARLOTTESVILLE EAST             |                            |  |

| Additional Property Inform   | mation   |
|--|--|
| Architecture Setting:  | Urban  |
| Acreage:   | No Data  |
| Site Description:  |  |
| a fieldstone along the front (no   | ouse is located on the east side of 8th Street NW, halfway between Anderson and Page Streets. There is<br>rthwest) property line. There is a large, deciduous tree in the southwest corner of the lot and a shed to<br>of the property is surrounded by a thin, metal and chicken-wire fence. This property consists of a house  |
| Surveyor Assessment:   |  |
| Viewer 2020). However, this h<br>and into today, indicating it wa<br>Company 1950). A rear deck o    | narlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS<br>ouse first appears on the 1920 Sanborn Map with the same footprint it has on the other Sanborn Maps<br>s built prior to 1920 (Sanborn Map Company 1920; Sanborn Map Company 1929; Sanborn Map<br>n the south corner of the house was installed c. 2017, at the same time as the rear shed (USGS 2016;<br>s owned by Lucille Anderson from 1962 to 1991 (City of Charlottesville GIS Viewer 2020). |
| compromised through replacen   | integrity of location and setting. The integrity of design, materials, and workmanship has been<br>nent windows, replacement cladding, and the addition of the rear deck. This property retains excellent<br>tion. Overall, this property retains good integrity.  |
| is located in the potential 10th<br>study is recommended to detern<br>areas of Ethnic Heritage, Comr | as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further mine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the nunity Planning and Development, and Social History, and under Criterion C in the area of ludes one contributing primary resource and one non-contributing secondary resource.   |
| Surveyor Recommendation:   | Recommended Not Eligible   |
| Ownership  |  |
| <b>Ownership Category</b><br>Private   | Ownership Entity<br>No Data  |

| Primary Resource Infor    | mation                                    |
|---------------------------|---|
| <b>Resource Category:</b> | Domestic                                  |
| <b>Resource Type:</b>     | Single Dwelling                           |
| NR Resource Type:         | Building                                  |
| Date of Construction:     | ca 1920                                   |
| Date Source:              | Мар                                       |
| Historic Time Period:     | World War I to World War II (1917 - 1945) |
| Historic Context(s):      | Domestic                                  |
| Other ID Number:          | No Data                                   |
| Architectural Style:      | Vernacular                                |
| Form:                     | T-Plan                                    |
|                           |   |

## Virginia Department of Historic Resources Architectural Survey Form

| Number of Stories:   | 2.0        |
|----------------------|------------|
| Condition:           | Good       |
| Threats to Resource: | None Known |

#### Architectural Description:

January 2020: This two-story house sits on a concrete foundation, is clad in aluminum siding, and has a cross-gabled roof covered in standing seam metal. There are two, interior, brick chimneys located on the ridgeline. The front (northwest) facing façade features an almost full-width, one-story, open porch with a hipped roof. The porch roof is supported by turned wood columns with decorative brackets and the porch has a concrete floor. The main entrance to the house is located in the middle of this façade. The rear (southeast) elevation features a one-story, wood deck on the south corner. This deck has wood railings and is accessed by wood stairs with wood railings. Visible fenestration includes six-oversix, double-hung, vinyl windows, most with fixed wood shutters; a single-leaf, wood door with a single-light and four stained-glass squares above and below.

#### **Exterior Components**

| <b>Component</b><br>Chimneys<br>Foundation<br>Porch<br>Structural System and<br>Exterior Treatment | <b>Component Type</b><br>Interior Central<br>Solid/Continuous<br>1-Story Full-Width<br>Wood Frame | <b>Material</b><br>Brick<br>Concrete<br>Wood<br>Aluminum | Material Treatment<br>Strecther Bond<br>Stuccoed/Parged<br>Posts<br>Siding |
|--|---|--|--|
| Windows  | Double-hung   | Vinyl  | No Data  |
| Roof   | Cross Gable   | Metal  | No Data  |

## **Secondary Resource Information**

### Secondary Resource #1

| <b>Resource Category:</b> | Domestic                       |
|---------------------------|--------------------------------|
| Resource Type:            | Shed                           |
| NR Resource Type:         | Building                       |
| Date of Construction:     | ca 2017                        |
| Date Source:              | Map                            |
| Historic Time Period:     | Post Cold War (1992 - Present) |
| Historic Context(s):      | Domestic                       |
| Other ID Number:          | No Data                        |
| Architectural Style:      | No discernible style           |
| Form:                     | Rectangular                    |
| Number of Stories:        | 1.0                            |
| Condition:                | Excellent                      |
| Threats to Resource:      | None Known                     |
|                           |                                |

#### **Architectural Description:**

January 2020: This shed is clad in vertical wood siding and has a shed roof covered in metal roofing. It also has a porch on the northwest façade. This porch has a shed roof and is supported by square, wood posts. Visible fenestration includes fixed, stained-glass, wood windows with multiple lights; and a single-leaf, vertical wood door.

#### **Exterior Components**

| Component             | <b>Component Type</b> | Material | Material Treatment |
|-----------------------|-----------------------|----------|--------------------|
| Porch                 | 1-Story Full-Width    | Wood     | Posts              |
| Structural System and | Wood Frame            | Wood     | Vertical Board     |
| Exterior Treatment    |                       |          |                    |
| Windows               | Fixed                 | Wood     | No Data            |
| Roof                  | Shed                  | Metal    | No Data            |

| Historic District Information   | 1       |
|---------------------------------|---------|
| Historic District Name:         | No Data |
| Local Historic District Name:   | No Data |
| Historic District Significance: | No Data |

# **CRM Events**

| Project Review File Number:   | No Data   |
|---|---|
| nvestigator:  | Erin Que  |
| Organization/Company:   | The 106 Group Ltd.  |
| Photographic Media:   | Digital   |
| Survey Date:  | 2/5/2020  |
| Ohr Library Report Number:  | No Data   |
| Project Staff/Notes:  |   |
| Erin Que, Principal Investigat<br>Holly Good, Architectural His<br>Saleh Miller, Sr. Architectura   | or and Sr. Architectural Historian<br>storian<br>I Historian  |
| Project Bibliographic Informati   | on:   |
| City of Charlottesville GIS Vi<br>2020 Property Record. Electro   | ewer<br>nic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.  |
| Hill Directory Co.  |   |
|   | Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.   |
| 1931, 1940, 1950, 1959 Hill's<br>National Environmental Title   |   |
| <ul> <li>1931, 1940, 1950, 1959 Hill's</li> <li>National Environmental Title</li> <li>1963-2016 Historical Aerial P</li> <li>March 19, 2020.</li> <li>Neighborhood Development S</li> </ul>   | Research, LLC [NETR]<br>hotograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed             |
| <ul> <li>1931, 1940, 1950, 1959 Hill's<br/>National Environmental Title<br/>1963-2016 Historical Aerial P<br/>March 19, 2020.</li> <li>Neighborhood Development S<br/>2012-2016 The 10th and Page<br/>Virginia.</li> <li>Sanborn Map Company</li> </ul> | Research, LLC [NETR]<br>hotograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed<br>Services |

# **Bibliographic Information**

**Bibliography:** 

No Data

#### **Property Notes:**

No Data

