Architectural Survey Form

DHR ID: 104-5773 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 213 9th Street NW

Property Evaluation Status

Property Addresses

Current - 213 9th Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This two-story house sits on the east side of 9th Street NW at the intersection of Paoli Street and 9th Street NW. There is a low, concrete and brick retaining wall along the northwest property line that continues along the southwest property line. There is a concrete patio on the northeast elevation of the house. The gravel parking pad near the north corner seems to belong to the neighboring house to the north. There is a large tree in the rear of the property as well as a metal, chain-link fence that runs along the southeast property line. This property consists of a house.

Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was constructed in 1947 (City of Charlottesville GIS Viewer 2020). This is supported by the Sanborn Maps, since the building first appeared on the 1950 Sanborn Map with the same general footprint it maintains today (Sanborn Map Company 1950). The rear, open, partial-width porch present in this map was enclosed in the early 2000s. Also at this time, a shed roof awning was added to the north end of the southeast elevation, likely above a basement entrance (Sanborn Map Company 1950; USGS 1994; USGS 2003; USGS 2005). This property was owned by Virginia Banks Carrington from 1962 to 2003 (City of Charlottesville GIS Viewer 2020).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship has been compromised by the rear porch changes, some replacement windows, and the addition of the front awnings. This property retains good integrity of feeling and association. Overall, this property retains fair integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1947

Date Source: Local Records

Historic Time Period: The New Dominion (1946 - 1991)

Historic Context(s): Domestic
Other ID Number: No Data

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5773

Architectural Style:VernacularForm:RectangularNumber of Stories:2.0Condition:GoodThreats to Resource:None Known

Architectural Description:

January 2020: This two-story house sits on a concrete block foundation, is constructed of concrete block, and has a front-gabled roof covered in asphalt shingles. There is an exterior, concrete block chimney on the northeast elevation; it has some brick infill. The front (northwest) facing façade features a partial-width, one-story, open porch with a hipped roof. The porch roof is supported by square wood posts and the porch is accessed by concrete block steps, covered in green felt, with metal railings. This porch and all of the windows on this façade have metal, shedroof awnings. The southeast elevation features a half-width, enclosed porch with a shed roof in the south end and a shed roof awning in the north end (USGS 2016). All of the windows on the house also have sills comprised of header bricks. Visible fenestration includes six-over-six, double-hung, wood windows, some with metal storm windows/screens; six-over-six, double-hung, vinyl windows, some with metal storm windows/screens; and a single-leaf, wood door with two lights, and a metal and glass storm door.

Exterior Components

Component Type Component Material **Material Treatment** Chimneys Exterior End Concrete Block Foundation Solid/Continuous Concrete Block 1-Story Partial Width Porch Wood Square Structural System and Masonry Concrete Block **Exterior Treatment** Wood No Data Windows Double-hung Roof Front Gable Asphalt No Data

Secondary Resource Information

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: *No Data* **Investigator:**Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media:DigitalSurvey Date:2/5/2020Dhr Library Report Number:No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5773

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville,

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

