Architectural Survey Form

DHR ID: 104-5775 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 215 9th Street NW

Property Evaluation Status

Property Addresses

Current - 215 9th Street NW

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This two-story house is located on the east side of 9th Street NW at the Paoli Street and 9th Street NW intersection. The front of the property has been covered with pebbled concrete in a circle, and the southeast property line features a gravel parking pad. There is a shed to the southeast of the house. This property consists of a house and a shed.

Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). It first appears on the 1929 Sanborn Map as 213 Alfonsa Street with the same footprint it retains today (Sanborn Map Company 1929; Sanborn Map Company 1950). In these maps, the rear wing is only one story tall and it extended slightly beyond the southwest elevation. A second story was added to the wing and it was shortened to be full width c. 2019. The shed in the rear of the property was constructed c. 2019, along with the new rear deck, and the house was repainted around the same time (USGS 2017; City of Charlottesville GIS Viewer 2020).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship has been compromised by replacement windows, significant changes to the rear wing, and the new deck. This property retains excellent integrity of feeling and association. Overall, this property retains fair integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1925

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: Rectangular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5775

Number of Stories: 2.0
Condition: Remodeled
Threats to Resource: None Known

Architectural Description:

January 2020: This two-story house sits on a stuccoed foundation, is clad in stucco, and has a hipped roof clad in asphalt shingles. The front (northwest) facing façade includes an almost full-width, one-story, open porch with a hipped roof covered in new standing seam copper. The porch roof is supported by square wood columns and the porch has a concrete floor. The rear (southeast) elevation features a now two-story rear wing, built in kind with the rest of the building. There is a one-story wood deck at the southeast end of the southwest elevation. The deck has wood railings and is accessed by wood steps. Visible fenestration includes two-over-two, double-hung, vinyl windows, some with screens; two-light fixed windows; a single-leaf wood door with a single-leaf wood door with a large light and a transom.

Exterior Components

Component Component Type Solid/Continuous **Material Treatment** Material Foundation Unknown Stuccoed/Parged 1-Story Full-Width Porch Wood Square Structural System and Wood Frame Unknown Stuccoed Exterior Treatment Double-hung Vinyl No Data Windows Roof Hipped Asphalt No Data

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 2019Date Source:Map

Historic Time Period: Post Cold War (1992 - Present)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: Rectangular
Number of Stories: 1.0
Condition: Excellent
Threats to Resource: None Known

Architectural Description:

January 2020: The rear (southeast) of this property has a one-story shed. This shed rests on a wood pallet on concrete blocks, is clad in vertical wood siding, and has a side-gabled roof covered in asphalt shingles. The front-facing (northwest) façade of the shed features a front-gabled dormer with a fanlight. The other windows are pedimented. Visible fenestration includes four-over-one, double-hung, vinyl windows some with screens; a fixed wood fanlight; and double-leaf wood doors with four-lights at the top.

Exterior Components

Component Component Type Material **Material Treatment** Dormer Gable Wood No Data Foundation No Data Piers Wood Wood Frame Vertical Board Structural System and Wood Exterior Treatment Double-hung Vinyl No Data Windows Asphalt Roof Side Gable No Data

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5775

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

