Property Names			
Name Explanation Function/Location	Name House, 703 Anderson Street	Property Evaluation Status	
Property Addresses			
Current - 703 Anderson Stre	eet		
County/Independent City(s):	Charlottesville (Ind. City)		
Incorporated Town(s):	No Data		
Zip Code(s):	22903		
Magisterial District(s):	No Data		
Tax Parcel(s):	No Data		
USGS Quad(s):	CHARLOTTESVILLE EAST		

Additional Property Info	ormation
Architecture Setting:	Urban
Acreage:	No Data
Site Description:	
block retaining wall along the block retaining wall along the block and the block retaining wall along the block retaining w	y house is located on the north side of Anderson Street, just west of 7th Street NW. There is a low concrete ne southwest property line, topped by a metal, chain link fence that extends around the whole property. trees dotted throughout the property. This property has a shed in the east corner, and a carport in the north way off of 7th Street NW. This property consists of a house, a shed, and a carport.
Surveyor Assessment:	
Viewer 2020). This build da Map Company 1950; NETR	Charlottesville City Property Records, this house was constructed in 1955 (City of Charlottesville GIS te is supported by aerial photographs, and the house does not appear on the 1950 Sanborn Map (Sanborn & 1963). The shed in the northeast corner of the lot was constructed in 2010 (USGS 2009; USGS 2011). t corner of the lot was constructed prior to 1994, though the exact date is difficult to see on aerial NETR 1968).
compromised by replacement	ntegrity of location and setting. The integrity of design, materials, and workmanship has been nt cladding on the rear wing, replacement windows. This property retains excellent integrity of feeling and operty retains good integrity.
is located in the potential 10 study is recommended to de areas of Ethnic Heritage, Co	led as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further termine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the pommunity Planning and Development, and Social History, and under Criterion C in the area of includes one contributing primary resource and two non-contributing secondary resources.
Surveyor Recommendation:	Recommended Not Eligible
Ownership	
<b>Ownership Category</b> Private	<b>Ownership Entity</b> No Data

Primary Resource Information		
<b>Resource Category:</b>	Domestic	
<b>Resource Type:</b>	Single Dwelling	
NR Resource Type:	Building	
Date of Construction:	1955	
Date Source:	Local Records	
Historic Time Period:	The New Dominion (1946 - 1991)	
Historic Context(s):	Domestic	
Other ID Number:	No Data	
Architectural Style:	Minimal Traditional	
Form:	Square	
i vi m.	σμασ	

# Virginia Department of Historic Resources Architectural Survey Form

Number of Stories:	1.0
Condition:	Good
Threats to Resource:	None Known

# Architectural Description:

January 2020: This one-story house sits on an exposed concrete block foundation, is constructed of concrete block with brick quoins, and has a side-gabled roof with a rear, one-story, shed-roof wing to the northeast (rear). There is an interior brick and concrete block chimney on the southwest roof slope. There is a front-facing gable projection on the southwest-facing façade in the east end. In the west end, the facade features a partial-width, engaged, wood porch with a shed roof and canvas rolled screens. This porch roof is supported by turned wood columns. The porch sits on a concrete block foundation, has wood railings, and is accessed by concrete steps. The rear wing is clad in vinyl siding. Visible fenestration includes one-over-one, double-hung, vinyl windows; a fixed, vinyl picture window flanked by one-over-one, double-hung, vinyl windows; a double-leaf wood door with large lights; and a nine-light, single-leaf, wood door with a metal and glass storm door.

#### **Exterior Components**

<b>Component</b>	Component Type	<b>Material</b>	<b>Material Treatment</b>
Chimneys	Interior End	Concrete	Block
Foundation	Solid/Continuous	Concrete	Block
Porch	Inset/Engaged	Wood	Turned
Structural System and	Masonry	Concrete	Block
Exterior Treatment Windows Roof	Double-hung Side Gable	Vinyl Asphalt	No Data No Data

# **Secondary Resource Information**

# Secondary Resource #1

Resource Category:	Domestic
Resource Type:	Shed
NR Resource Type:	Building
Date of Construction:	ca 2010
Date Source:	Map
Historic Time Period:	Post Cold War (1992 - Present)
Historic Context(s):	Domestic
Other ID Number:	No Data
Architectural Style:	No discernible style
Form:	Square
Number of Stories:	1.0
Condition:	Good
Threats to Resource:	None Known

#### **Architectural Description:**

January 2020: There is a one-story shed in the east corner of the lot. It sits on a rough, concrete block foundation, is clad in plywood panels, and has a front-gabled roof covered in asphalt shingles. There is no visible fenestration.

#### **Exterior Components**

<b>Component</b>	<b>Component Type</b>	<b>Material</b>	<b>Material Treatment</b>
Foundation	Solid/Continuous	Concrete	Block
Structural System and	Wood Frame	Plywood/Particle Board	Panels
Exterior Treatment Roof	Front Gable	Asphalt	No Data

# Secondary Resource #2

Resource Category:	Domestic
Resource Type:	Carport
NR Resource Type:	Structure
Date of Construction:	ca 1990
Date Source:	Map
Historic Time Period:	The New Dominion (1946 - 1991)
Historic Context(s):	Domestic
Other ID Number:	No Data

# Virginia Department of Historic Resources

Architectural Survey Form

Architectural Style:	No discernible style
Form:	Rectangular
Number of Stories:	No Data
Condition:	Good
Threats to Resource:	None Known

#### **Architectural Description:**

January 2020: There is a carport located in the north corner of this property. It is supported by square wood posts, has a front-gabled roof covered in asphalt shingles. The gable ends are clad in vinyl siding. There is no visible fenestration and it is an open structure with screen covers.

# **Historic District Information**

Historic District Name:	No Data
Local Historic District Name:	No Data
Historic District Significance:	No Data

# **CRM Events**

# Event Type: Survey: Phase I/Reconnaissance

Project Review File Number:	No Data
Investigator:	Erin Que
Organization/Company:	The 106 Group Ltd.
Photographic Media:	Digital
Survey Date:	2/5/2020
Dhr Library Report Number:	No Data

#### **Project Staff/Notes:**

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

# **Project Bibliographic Information:**

City of Charlottesville GIS Viewer 2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR] 1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Bibliographic Information**

### **Bibliography:**

No Data

# **Property Notes:**

No Data

