Architectural Survey Form

DHR ID: 104-5798 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 801 Anderson Street

Property Evaluation Status

Property Addresses

Current - 801 Anderson Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This one-and-a-half story house is located on the north corner of Anderson Street and 8th Street NW. There is extensive vegetation to the southwest of this property, obscuring that side of the building, as well as large deciduous trees in the front of the property and in the rear as well. The southwest (front) property line is lined by a low, concrete-block retaining wall, which extends around the southeast side of the lot. The rear is accessible through an alleyway off of 8th Street NW. This property consists of a house.

Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this property was constructed in 1925 and has been owned by the same family, the Morris family, since 1976 (Charlottesville City GIS Viewer 2020). However, the house first appears on the 1920 Sanborn Map with the same footprint it retains today, except with a wrap-around porch (Sanborn Map Company 1920). This porch appears to have been shortened to only a front porch in the early 1960s (NETR 1968). In the 1929 and 1950 Sanborn Maps, this property is accompanied by two small sheds in the northwest corner, both of which were demolished between 1950 and 1963 (Sanborn Map Company 1950; NETR 1963).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship has been compromised by replacement cladding. This property retains good integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

vate No Da

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:ca 1920Date Source:Map

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5798

No Data **Number of Stories:** 15 Condition: Good None Known **Threats to Resource:**

Architectural Description:

January 2020: This one-and-a-half-story house sits on a concrete block foundation, is clad in vinyl siding, and has a hipped roof covered in asphalt shingles. The front (southwest) facing façade features a hipped roof dormer clad in vinyl siding and a full-length, one-story, open porch with a shed roof. The porch also rests on a concrete block foundation, which is inhabitable as there are basement windows. The porch roof is covered in standing seam metal and supported by metal filigree columns. The porch has metal railings, and is accessed by concrete block steps. The southeast elevation also features a hipped dormer clad in vinyl siding. All visible windows on the first story have fixed wood shutters. There is a partial-width, one-story, shed-roof wing in the center of the northeast elevation. It contains a secondary entrance and is accessed by wood stairs with wood railings. Visible fenestration includes two-over-two, double-hung, wood windows, some with faux dividers and some with metal screens; one-over-one, double-hung, wood windows; and a single-leaf, wood door with a metal and glass screen door.

Exterior Components

Component Component Type Material **Material Treatment** Dormer Hipped Vinyl Foundation Solid/Continuous Concrete Block 1-Story Full-Width Cast Metal Supports Porch Metal Structural System and Wood Frame Vinyl Siding

Exterior Treatment

Windows Double-hung Wood No Data Roof Asphalt No Data Hipped

Secondary Resource Information

Historic District Information

Historic District Name: No Data **Local Historic District Name:** No Data **Historic District Significance:** No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

May 21, 2020 Page: 2 of 3 Architectural Survey Form Other DHR ID: No Data

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

DHR ID: 104-5798

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

May 21, 2020 Page: 3 of 3

