Architectural Survey Form

DHR ID: 104-5804 Other DHR ID: No Data

#### **Property Information**

**Property Names** 

Name Explanation Name

Function/Location House, 814 Anderson Street

**Property Evaluation Status** 

Property Addresses

Current - 814 Anderson Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

## **Additional Property Information**

Architecture Setting: Urban
Acreage: No Data

**Site Description:** 

January 2020: This two-story house is located on the south side of Anderson Street, east of 9th Street NW. There are large deciduous trees to the east and west of the property, as well as along the rear property line. The property is surrounded by a white picket fence except for the northeast property line, which has no fencing. This property consists of a house.

#### Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). This is supported through the Sanborn Maps, since the building first appears on the 1929 Sanborn Map, which it maintained into the 1950 Sanborn Map (Sanborn Map Company 1929; Sanborn Map Company 1950). In these maps, the rear wing is only one-story tall, but at an unknown date this was expanded to be two stories (Sanborn Map Company 1950; USGS 2017). This house has a very similar footprint to 816 Anderson Street.

This property retains excellent integrity of location. The integrity of setting has been slightly compromised by the demolition of the house to the east in the 1990s and construction of a new house in 2000 (NETR 1994; City of Charlottesville GIS Viewer 2020). The integrity of design, materials, and workmanship has been compromised by replacement windows, replacement cladding, and the second story expansion of the rear wing. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Do

# **Primary Resource Information**

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1925

Date Source: Local Records

**Historic Time Period:** World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5804

Rectangular **Number of Stories:** 2.0 Good None Known **Threats to Resource:** 

#### **Architectural Description:**

January 2020: This two-story house is clad in vinyl siding and has a hip-on-hipped roof covered in new standing seam metal. There is a stuccoed, interior chimney with a vented top located on the northeast roof slope near the ridgeline in the center of the roof. The front (northeast) facing façade features a full-width, one-story, open porch with a hipped roof covered in asphalt shingles. The porch roof is supported by square wood columns. The porch has wood railings and is accessed by a concrete step. The main entrance for this house is located at the east end of this façade. The windows on the façade have fixed wood shutters. The rear wing of the house is slightly narrower than the front wing. There is a full-width, one-story, large wood deck on the rear (southwest) elevation of the house accessed by wood stairs with wood railings. There is also a second-story balcony at the west end (USGS 2017) Visible fenestration includes one-over-one, double-hung vinyl windows, some with metal storm windows; and a single-leaf, wood door with a metal screen door and a transom.

#### **Exterior Components**

Component Component Type Material **Material Treatment** Stuccoed/Parged Chimneys Interior Central Unknown 1-Story Full-Width Porch Wood Square Wood Frame Structural System and Vinyl Siding **Exterior Treatment** Windows Double-hung Vinyl No Data Roof Hipped Metal No Data

#### **Secondary Resource Information**

### **Historic District Information**

**Historic District Name:** No Data **Local Historic District Name:** No Data **Historic District Significance:** No Data

## **CRM Events**

## Event Type: Survey:Phase I/Reconnaissance

**Project Review File Number:** No Data Erin Que Investigator:

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital 2/5/2020 **Survey Date: Dhr Library Report Number:** No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

#### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville,

May 21, 2020 Page: 2 of 3 Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5804

Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Bibliographic Information**

Bibliography:

No Data

**Property Notes:** 

No Data

May 21, 2020 Page: 3 of 3

