Architectural Survey Form

DHR ID: 104-5811 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 905 Anderson Street

Property Evaluation Status

Property Addresses

Current - 905 Anderson Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This two-story house is located on the north side of Anderson Street. There is a partial-width, painted, concrete block retaining wall on the southeast side of the property. There are box hedges on top of this wall that continue down the northwest and southeast property lines. There is a shed in the northwest corner of the lot and a large deciduous tree between the house and the shed. This property consists of a house and a shed.

Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). This is supported by the Sanborn Maps, since the building first appears in the 1929 Sanborn Map and continues with the same footprint in the 1950 Sanborn Map (Sanborn Map Company 1929; Sanborn Map Company 1950). In 1929, it was identified as a store (Sanborn Map Company 1929). The footprint of the house has not changed over time. The current shed was built c. 2019, replacing a previous shed constructed between 1994 and 2003 (USGS 1994; USGS 2003; City of Charlottesville GIS Viewer 2020).

This property retains good integrity of location and setting, with the setting mildly compromised by the construction of the house to the northwest of the property in the early 1960s (NETR 1963; NETR 1964). The integrity of design, materials, and workmanship has been mildly compromised by replacement windows and replacement cladding. This property retains good integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

vate No Da

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1925

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic

Other ID Number: No Data

Architectural Style: Vernacular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5811

Form: Rectangular
Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: This two-story house sits on a concrete block foundation, is clad in vinyl siding, and has a front-gabled roof covered in asphalt shingles. The front (southwest) facing façade features a full-width, one-story, open porch with a shed roof covered in asphalt shingles. The porch roof is supported by square wood posts. The porch has turned wood railings and is accessed by concrete steps with metal railings. The main entrance is located at the west end of this façade. The rear (northeast) elevation has a partial-width, shed-roof, one-story wing. Visible fenestration includes one-over-one, double-hung, metal windows, some with metal screens; and a single-leaf, wood door with two lights, and a metal and glass storm door.

Exterior Components

Component Component Type Material **Material Treatment** Foundation Solid/Continuous Concrete Wood 1-Story Full-Width Square Porch Structural System and Wood Frame Vinyl Siding **Exterior Treatment** Double-hung No Data Windows Metal Roof Front Gable Asphalt No Data

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 2019Date Source:Map

Historic Time Period: Post Cold War (1992 - Present)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: There is a shed to the northwest of the house. This shed is one-story, clad in vertical wood siding, and has a front-gabled roof covered in asphalt shingles. Visible fenestration includes wood paneled swing doors.

Exterior Components

ComponentComponent TypeMaterialMaterial TreatmentStructural System and
Exterior TreatmentWood FrameWoodVertical BoardExterior TreatmentFront GableAsphaltNo Data

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5811

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

