Architectural Survey Form

DHR ID: 104-5816 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 914 Anderson Street

Property Evaluation Status

Property Addresses

Current - 914 Anderson Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This two-story house is located on the south side of Anderson Street, halfway between 10th and 9th Streets NW. The whole property is enclosed by a metal, chain-link fence, and there are large deciduous trees and shrubs dotted throughout the lot. There is an unpaved parking spot to the southeast of the house, and a low, concrete wall along the northeast property line. This property consists of a house.

Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). However, a house with a very similar footprint appears on the 1920 Sanborn Map. In the 1929 and 1950 Sanborn Maps, there is a second-story, open porch on the northeast elevation (Sanborn Map Company 1920; Sanborn Map Company 1929; Sanborn Map Company 1950). This has since been enclosed at an unknown date.

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship has been compromised by replacement windows, replacement cladding, and the enclosure of the second-story porch. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:ca 1920Date Source:Map

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: Rectangular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5816

Number of Stories:2.0Condition:GoodThreats to Resource:None Known

Architectural Description:

January 2020: This two-story house is clad in asbestos siding and has a cross-gabled roof covered in standing seam metal. There is an interior, brick chimney in the center of the ridgeline. The front (northeast) facing façade features a full-width, one-story, open porch with a hipped roof. The porch roof is supported by tapered, square wood columns on brick piers and the porch has brick knee walls at the porch ends. The front-facing gable on the façade projects slightly from the rest of the house. The main entrance is located at the east end. Visible fenestration includes one-over-one, double-hung, vinyl windows, some with screens; and a single-leaf, wood door with a metal and glass storm door.

Exterior Components

ComponentComponent TypeMaterialMaterial TreatmentChimneysInterior CentralBrickStrecther BondPorch1-Story Full-WidthWoodColumns/Posts on PiersStructural System andWood FrameAsbestosSiding

Exterior Treatment

Windows Double-hung Vinyl No Data
Roof Cross Gable Metal No Data

Secondary Resource Information

Historic District Information

Historic District Name:No DataLocal Historic District Name:No DataHistoric District Significance:No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number:No DataInvestigator:Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media:DigitalSurvey Date:2/5/2020Dhr Library Report Number:No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company

1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

May 21, 2020 Page: 2 of 3

DHR ID: 104-5816 Architectural Survey Form Other DHR ID: No Data

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

May 21, 2020 Page: 3 of 3

