Architectural Survey Form

Other DHR ID: No Data

DHR ID: 104-5818

### **Property Information**

**Property Names** 

Name Explanation Name

Function/Location House, 916 Anderson Street

**Property Evaluation Status** 

Property Addresses

Current - 916 Anderson Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

## **Additional Property Information**

Architecture Setting: Urban
Acreage: No Data

**Site Description:** 

January 2020: This two-story house is located on the south side of Anderson Street, between 10th and 9th Streets NW. The southwest side of the property is almost entirely obscured by trees and bushes. The northeast property line is bordered by a low, concrete wall, while the northwest property line is bordered by a wood fence, which wraps around the rear of the lot. This property includes a house.

#### Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). This house first appears in the 1929 Sanborn Maps with the same footprint as today, including an open porch on the southwest elevation that is not visible today, if it still exists (Sanborn Map Company 1929). This footprint is clear in the 1950 Sanborn Map, and remains unchanged today (Sanborn Map Company 1950).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship has been compromised by replacement windows and potential replacement cladding. This property retains good integrity of feeling and association, compromised by the overgrowth of trees and bushes in the northwest corner of the lot. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

**Date Source:** 

Ownership Category Ownership Entity

Private No Data

# **Primary Resource Information**

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1925

**Historic Time Period:** World War I to World War II (1917 - 1945)

Local Records

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: Rectangular

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5818

Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

### **Architectural Description:**

January 2020: The house sits on a concrete foundation, is clad in wood siding, and has a cross-gabled roof covered in asphalt shingles. The front (northeast) facing façade has a full-width, one-story, open porch with a shed roof covered in asphalt shingles. The porch roof is supported by square wood columns, and the porch is accessed by a slate walkway. The porch has wood railings and sits on a concrete foundation. The main entrance for this house is located at the east end of the facade. A rear, first-story wood deck is minimally visible from the public right-of-way. There is an interior chimney located on the ridgeline of this roof. Visible fenestration includes six-over-six, double-hung, vinyl windows; and a single leaf wood door with a metal and glass storm door.

#### **Exterior Components**

Roof

Component Component Type Solid/Continuous Material Material Treatment Foundation Concrete Uncoursed 1-Story Full-Width Square Porch Wood Structural System and Wood Frame Wood Siding Exterior Treatment Vinyl Windows Double-hung No Data

Asphalt

No Data

## **Secondary Resource Information**

#### **Historic District Information**

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

## **CRM Events**

## Event Type: Survey:Phase I/Reconnaissance

**Project Review File Number:** *No Data* **Investigator:**Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media:DigitalSurvey Date:2/5/2020Dhr Library Report Number:No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Side Gable

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

## **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5818

1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]
1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

## **Bibliographic Information**

## Bibliography:

No Data

## **Property Notes:**

No Data

May 21, 2020 Page: 3 of 3

