Architectural Survey Form

DHR ID: 104-5828 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 1100 Gordon Avenue

Property Evaluation Status

Property Addresses

Current - 1100 Gordon Avenue

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

2016: This property was surveyed in 2012-2016 by City of Charlottesville Neighborhood Development Services. The front of the lot has a concrete walkway leading down from the sidewalk to the entrance, as the house sits lower than the street. Privet hedges line the front and side yards. There are two standing seam metal, gabled roof outbuildings in the side yard (one of which faces the alley and is likely a former garage). A gravel alley runs north to south on the west side of the property. There is a large oak tree at the corner of West and 11th in the yard.

Surveyor Assessment:

2016: Ownership History

C.C. Cocke sold the property to Jeff and Annie Jackson on June 1, 1915 (County 160-26). Jeff and Annie Jackson died interstate and their children inherited the property but all sold to sister Nannie Luck. For example, daughter Bessie Cosby granted the property to Nannie Luck in 1927 City 59-106). The other deeds in this transaction are: 60-271, 61-360, 62-456, and 62-457. Edward O. McCue Jr. became trustee of the property in 1928(City 63-27). Citizens Bank and Trust became trustee in 1935(City 87-333). E.L. Bailey bought the property in 1939(City 99-397). The Baileys owned the house through the 1970s.

Social History

Jeff Jackson, an African American laborer and his wife Annie Jackson lived in the house from 1919 until 1926. Their daughter Nannie Luck, a cook, lived in the house with her husband John Luck, a bellman, from 1927 until 1933. The house was rented to another African American family in the late 1930s until the 1940s, Peyton Gross, a laborer, and his wife Amanda Gross. In 1945, Richard Norris, an African American laborer, and his wife Estelle Norris, lived in the house. Estelle lived there alone as a widow after Richard's death from 1950 until 1955. William Coleman, a painter, and his wife Margret Coleman lived there from 1956 until 1964.

Statement of Significance

This 20th century single-family dwelling has a unique below grade, large open site and two substantial older outbuildings. The original material of the house are well preserved, windows, doors, porch, and roof all seem intact.

2020: This property is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource, one contributing secondary resource, and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:ca 1919

May 21, 2020 Page: 1 of 4

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5828

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data
Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

2016: This three-bay, two-story, brick house was built around 1919. The current dwelling has a hipped, standing seam metal roof and paired brick exterior end chimneys. Across the façade is a one-bay, hipped standing seam metal roof porch with a parged concrete foundation, and decorative wood supports. There is a one-bay, one-story gabled kitchen addition built in 1964 on the west end of the house. The front-facing windows are 2/2 wood sash with wood louvered shutters.

Exterior Components

Component Component Type Material **Material Treatment** Roof Hipped Metal Exterior End Strecther Bond Chimneys Brick 1-Story Partial Width Porch Wood Turned Windows Double-hung Wood No Data Structural System and Masonry Brick Stretcher Bond **Exterior Treatment**

Secondary Resource Information

Secondary Resource #1

Resource Category: Domestic

Resource Type: Outbuilding, Domestic

NR Resource Type: Building
Date of Construction: ca 1960
Date Source: Map

Historic Time Period: The New Dominion (1946 - 1991)

Historic Context(s): Domestic **Other ID Number:** *No Data*

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

2016: There is a standing seam metal, gabled roof outbuilding in the side yard. It faces the alley and is likely a former garage.

Exterior Components

Component
Structural System andComponent Type
UnknownMaterial
MetalMaterial Treatment
Panels

Exterior Treatment

Roof Front Gable Metal No Data Roof Shed Metal No Data

Secondary Resource #2

Resource Category: Domestic

Resource Type: Outbuilding, Domestic

NR Resource Type: Building
Date of Construction: ca 2009
Date Source: Map

Historic Time Period: Post Cold War (1992 - Present)

May 21, 2020 Page: 2 of 4

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5828

Historic Context(s): Domestic Other ID Number: No Data

Architectural Style: No discernible style

No Data Form: 1.0 **Number of Stories: Condition:** Good Threats to Resource: None Known

Architectural Description:

2016: There is another standing seam metal, gabled roof outbuilding in the side yard.

Exterior Components

Component Component Type Material **Material Treatment**

Side Gable Roof Metal Structural System and Plywood/Particle Board Panels Unknown Exterior Treatment Jalousied Unknown No Data Windows

Historic District Information

Historic District Name: No Data **Local Historic District Name:** No Data **Historic District Significance:** No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

May 21, 2020 Page: 3 of 4

DHR ID: 104-5828 Other DHR ID: No Data

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

May 21, 2020 Page: 4 of 4

