Architectural Survey Form

DHR ID: 104-5838 Other DHR ID: No Data

**Property Evaluation Status** 

## **Property Information**

**Property Names** 

Name Explanation Name

Current Name

Dairy Central Commercial, 946 Grady Avenue Monticello Dairy Function/Location Historic

**Property Addresses** 

Current - 946 Grady Avenue

County/Independent City(s): Charlottesville (Ind. City)

**Incorporated Town(s):** No Data Zip Code(s): 22903 **Magisterial District(s):** No Data Tax Parcel(s): No Data

CHARLOTTESVILLE EAST USGS Quad(s):

## **Additional Property Information**

Urban **Architecture Setting:** No Data Acreage:

**Site Description:** 

January 2020: This property was surveyed in 1983 for the City of Charlottesville Neighborhood Development Services. A site description was not prepared during this survey.

## **Surveyor Assessment:**

1983: In 1936, the Monticello Dairy purchased a block of 16 lots bounded by Grady Avenue, Tenth Street, West Street, and Wood Street (City DB 910238).Tax records show that the building was completed the next year. It was designed by Charlottesville Architect Elmer Burruss. There were extensive additions in 1947, 1959, and 1964, mostly at the rear of the building. The west wing was extended in 1959, and the front section of the wing beyond the original west wing was built in 1964.

January 2020: This property is an Individually Protected Property in the City of Charlottesville. The building is currently undergoing a major renovation. It is recommended not eligible for listing in the NRHP due to a loss of integrity. This property is also not recommended for inclusion in the potential 10th and Page Historic District due to a lack of association with the district's historical significance.

**Surveyor Recommendation:** Recommended Not Eligible

Ownership

Ownership Category **Ownership Entity** 

No Data

Associate

**Property Associate Name Property Associate Role** 

Elmer Burruss Architect

# **Primary Resource Information**

**Resource Category:** Agriculture/Subsistence

**Resource Type:** Dairy NR Resource Type: Building 1937 **Date of Construction: Date Source:** Local Records

**Historic Time Period:** World War I to World War II (1917 - 1945)

**Historic Context(s):** Subsistence/Agriculture

Other ID Number: No Data **Architectural Style:** Colonial Revival

Form: No Data

May 21, 2020 Page: 1 of 3 Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5838

Number of Stories:2.0Condition:RemodeledThreats to Resource:Development

#### **Architectural Description:**

1983: The Monticello Dairy Building consists of a two-storey central pavilion, with one-storey flanking wings. It is set on a low foundation without a water table. Wall construction is brick laid in 5-course American-with-Flemish bond. Concrete-capped parapets conceal flat roofs covered with tar-&-gravel. The central pavilion is five bays wide. Six two-storey engaged Tuscan columns support a massive entablature with dentil moulding on the frieze. Fluted pi Jasters flanking the entrance in the center bay support a smaller version of that entablature. Within this, there is a rectangular architrave around the round-arched entrance. The original door has been replaced, but the half-round fanlight remains. All windows are jack-arched and have concrete sills. There is a display window with a 12-light transom and moulded surrounds in each bay at the first level. Second level windows are 16-light metal fixed and hinged sash, without surrounds. The flanking wings are seven bays wide. Each bay is slightly recessed between piers. Windows match those at the second level of the central block. There is a cornice below the top of the parapet. The western wing has been extended six more bays. The extension is set back slightly from the original and matches it in all details. The front section of a wing beyond the original east wing matches it in most details, but the brick is laid in stretcher bond.

#### **Exterior Components**

ComponentComponent TypeMaterialMaterial TreatmentStructural System and<br/>Exterior TreatmentMasonryBrickAmerican/Common Bond

Windows Fixed Metal No Data Roof Flat Other No Data

## **Secondary Resource Information**

#### **Historic District Information**

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

#### **CRM Events**

## Event Type: Survey:Phase I/Reconnaissance

**Project Review File Number:** No Data **Investigator:** Erin Que

**Organization/Company:** The 106 Group Ltd.

Photographic Media:DigitalSurvey Date:2/5/2020Dhr Library Report Number:No Data

**Project Staff/Notes:** 

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

#### **Project Bibliographic Information:**

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, Ĭ950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5838

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

# **Bibliographic Information**

Bibliography:

No Data

## **Property Notes:**

No Data

May 21, 2020 Page: 3 of 3

