Architectural Survey Form Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 802 Page Street

Property Evaluation Status

DHR ID: 104-5865

Property Addresses

Current - 802 Page Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This one-story house is located on the south side of Page Street, just west of 8th Street NW. There are trees and vegetation along the southeast property line and another tree near the west corner of the lot. This property consists of a house.

Surveyor Assessment:

January 2020: According to the Charlottesville City Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). However, this property is not visible on the 1929 Sanborn Maps. The house does appear on the 1950 Sanborn Maps with its present-day footprint (Sanborn Map Company 1929; Sanborn Map Company 1950). Because the address is listed in the 1940 city directory, the house was likely built in the 1930s (Hill Directory Co. 1940).

This property retains good integrity of location and setting. The integrity of design, materials, and workmanship is slightly compromised by replacement windows. This property retains good integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:ca 1935Date Source:Map

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data
Number of Stories: 2.0
Condition: Fair

May 21, 2020 Page: 1 of 3

Architectural Survey Form

Other DHR ID: No Data

DHR ID: 104-5865

Threats to Resource: None Known

Architectural Description:

January 2020: This two-story house rests on a stuccoed foundation, is clad in stucco, and has a hipped roof with a centered front gable that is covered in standing seam metal. The northeast-facing façade features an almost full-width, one-story, open porch with a hipped roof that is supported by tapered wood columns. The porch is accessed via concrete steps with wood railings. The main entrance is at the east end of the porch. There is an interior brick chimney on the northwest roof slope. The southeast elevation features a two-story, front gable wall dormer that projects slightly from the main block, and is also clad in stucco. The rear (southwest) elevation features a one-story, shed roof wing on the southeast elevation of the wall dormer, with a one-story, shed roof, open porch. This porch is supported by wood posts with wood railings. Visible fenestration includes six-over-six, double-hung, vinyl windows; a sliding vinyl window; and a single leaf wood door with a metal and glass storm door.

Exterior Components

Component Material **Material Treatment** Component Type Strecther Bond Chimneys Interior Slope Brick Dormer Wall Stucco No Data Stuccoed/Parged Solid/Continuous Unknown Foundation 1-Story Full-Width Porch Wood Square Structural System and Unknown Wood Frame Stuccoed Exterior Treatment No Data Windows Double-hung Metal Roof Hipped Metal No Data

Secondary Resource Information

Historic District Information

Historic District Name: No Data **Local Historic District Name:** No Data **Historic District Significance:** No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

May 21, 2020 Page: 2 of 3 Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5865

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

May 21, 2020 Page: 3 of 3

