Virginia Department of Historic Resources Architectural Survey Form

		Property Information		
Property Names Name Explanation Current Name Function/Location Historic	Name Legal Aid Justice Center Office Building, 1000 Preston Avenue Southern Bakery Building	Property Evaluation Status		
Property Addresses				
Current - 1000 Preston Aver	nue			
County/Independent City(s):	Charlottesville (Ind. City)			
Incorporated Town(s):	No Data			
Zip Code(s):	22903			
Magisterial District(s):	No Data			
Tax Parcel(s):	No Data			
USGS Quad(s):	CHARLOTTESVILLE EAST			
Additional Property Info	rmation			
	rmation Urban			
Architecture Setting:				
	Urban			
Architecture Setting: Acreage: Site Description:	Urban No Data	ville. A site description was not prepared during this		
Architecture Setting: Acreage: Site Description: January 2020: This property v survey.	Urban No Data	ville. A site description was not prepared during this		
Architecture Setting: Acreage: Site Description: January 2020: This property v survey. Surveyor Assessment: 1983: The Columbia Baking (DB 105-431) and completed t 1952 & 1956. The bread bake	Urban No Data was surveyed in 1983 for the City of Charlottes Company, which had been in business in Charle the building the same year, according to tax rec d here was marketed under the "Southern" labe akery closed its Charlottesville plant in 1966 ar	ville. A site description was not prepared during this ottesville since 1928, purchased this tract in 1941 (City ords. Additions were made at the rear of the building in el, and title was transferred to Southern Bakeries Company id sold the building to Bruton & Co., a wholesale barber		

Surveyor	Recommendation:
Surveyor	Kecommenuation.

Recommen	ded Not Eligible
----------	------------------

Ownership Entity No Data

Ownership CategoryOwnerPrivateNo Date

Primary Resource Information

Resource Category:	Industry/Processing/Extraction
Resource Type:	Processing Plant
NR Resource Type:	Building
Date of Construction:	1940
Date Source:	Local Records
Historic Time Period:	World War I to World War II (1917 - 1945)
Historic Context(s):	Industry/Processing/Extraction
Other ID Number:	No Data
Architectural Style:	Colonial Revival
Form:	No Data
Number of Stories:	2.0
Condition:	Good
Threats to Resource:	None Known
Architectural Description:	

1983: The Southern Bakery Building consists of a 2-storey central entrance tower, facing the corner of Tenth Street and Preston Avenue, flanke d by 1-storey side wings which bend at a 45° angle to follow the two streets. Behind this single-pile Colonial Revival facade, a strictly utilitarian flat-roofed, I & 2-storey building fills in the square. The building is set on a low foundation with a band of vertical brick forming the water table. Wall construction ls of brick laid in Flemish bond. The entrance tower has a medium-pitched hip roof, covered with slate, with projecting eaves and an entablature with modillions and an unusually deep frieze. There are fluted corner pilasters. The double entrance doors and transom are replacements; the original arrangement was probably a single door with side-lights . Pilasters with inset panels support a cornice on consoles above the entrance. There is a large wheel window at the second level of the facade. The side wings are pilastered and have steep gable roofs, covered with slate, with close verges and an entablature with modillions that cover the shallow frieze. Windows have jack arches, brick sills, and louvered shutters. The 6-over-6 light double sashes have been replaced with 12-light fixed sashes. The wings are six bays long, with the 45° turn occurring between the first and second bays. Both of these bays are narrower than the others. The first bay has a small 8-light window without shutters. The -second bay has a single window, while each of the other bays has two separate windows . There is a garage door in the last bay on the eastern elevation. There is a dormer above each of these wider bays. Its walls are covered with weatherboarding and its facade originals were double-sash or casement.

Exterior Components

Component	Component Type	Material	Material Treatment
Foundation	Slab	Brick	Coursed
Structural System and	Masonry	Brick	English Bond
Exterior Treatment Dormer Windows	Gable Fixed	Aluminum Vinyl	No Data No Data

Secondary Resource Information

Historic District Information

Historic District Name:	No Data
Local Historic District Name:	No Data
Historic District Significance:	No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance		
Project Review File Number:	No Data	
Investigator:	Erin Que	
Organization/Company:	The 106 Group Ltd.	
Photographic Media:	Digital	
Survey Date:	2/5/2020	
Dhr Library Report Number:	No Data	
1		

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer 2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Virginia Department of Historic Resources Architectural Survey Form

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

