Architectural Survey Form

Other DHR ID: No Data

DHR ID: 104-5917

Property Information

Property Names

Name Explanation Name

Function/Location House, 1113 Rosser Avenue East

Property Evaluation Status

Property Addresses

Current - 1113 Rosser Avenue East

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This one-story house is located on the north side of Rosser Avenue East. There are large box hedges along the front and east property lines, as well as a large tree in the southeast corner of the property and more trees along the rear property line. There is also a small parking pad in the southeast corner of the lot. This property consists of a house.

Surveyor Assessment:

January 2020: According to Charlottesville City Property Records, this house was built in 1940 (City of Charlottesville GIS Viewer 2020). This is supported through Sanborn Maps (Sanborn Map Company 1929; Sanborn Map Company 1950). At the time of its construction, Rosser Avenue East was called Rose Avenue, an extension of Preston Avenue NW (Sanborn Map Company 1950). A rear deck was added in 2010 (USGS 2009; USGS 2011). Otherwise, this house has remained unchanged since its construction in 1940 (Sanborn Map Company 1950).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship have been mildly compromised by exterior material changes, replacement changes, and the rear deck addition. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1940

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5917

Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: This one-story house rests on a concrete block foundation with a partially exposed basement, is clad in aluminum siding, and has a front-gabled roof covered in asphalt shingles. The south (front) facing façade features an almost full-width, one-story, open porch with a shed roof that is supported by metal filigree columns with metal railings. It is accessed by concrete steps with wood railings. This façade also features a secondary basement entrance on the east side beneath the porch. The east elevation also has a secondary basement entrance. The north (rear) elevation has a partial-width wood deck. Visible fenestration includes a single-leaf, wood door with six-lights and a metal storm door; single-leaf wood doors; and six-over-six, double-hung, vinyl windows.

Exterior Components

ComponentComponent TypeMaterialMaterial TreatmentFoundationSolid/ContinuousConcreteBlockPorch1-Story Full-WidthNo DataCast Metal SupportsStructural System andWood FrameAluminumSiding

Exterior Treatment
Windows Double-hung Vinyl No Data
Roof Front Gable Asphalt No Data

Secondary Resource Information

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: *No Data* **Investigator:**Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media:DigitalSurvey Date:2/5/2020Dhr Library Report Number:No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company

May 21, 2020 Page: 2 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5917

1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]
1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

May 21, 2020 Page: 3 of 3

