Architectural Survey Form Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 1111 Rosser Avenue East

Property Evaluation Status

DHR ID: 104-5918

Page: 1 of 3

Property Addresses

Current - 1111 Rosser Avenue East

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This one-story house is located on the north side of Rosser Avenue East and the front of the property is surrounded by a chain link fence with a few box hedges dotted throughout. This property consists of a house and a shed.

Surveyor Assessment:

January 2020: According to the City of Charlottesville Property Records, this house was constructed in 1942 (City of Charlottesville GIS Viewer 2020). This is supported by Sanborn Maps (Sanborn Map Company 1929; Sanborn Map Company 1950). There is a shed in the northeast corner of the property, which was constructed around 2005, as well as a rear deck installed around 2012 (USGS 2003; USGS 2005; USGS 2011; USGS 2013). Otherwise, the house remains largely unchanged.

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship have been mildly compromised by the rear deck addition and replacement windows. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Condition:

May 21, 2020

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1942

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Good

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: Minimal Traditional

Form: Rectangular
Number of Stories: 1.0

DHR ID: 104-5918 Architectural Survey Form Other DHR ID: No Data

Threats to Resource: None Known

Architectural Description:

January 2020: This one-story house rests on a concrete block foundation, is constructed of concrete block, and has a front-gabled roof covered in asphalt shingles. There is an interior concrete block chimney on the east roof slope. The front (south) facing facade features an almost fullwidth, one-story, open porch with a shed roof supported by metal filigree columns with metal railings. This porch is accessed via concrete steps with metal railings. This facade features a secondary basement entrance on the east side below the porch. The east elevation also has a secondary basement entrance. The rear (north) elevation has a wood deck and a secondary entrance. Visible fenestration includes six-over-six, double-hung, metal windows with metal storm windows; single-leaf, vertical wood doors; and a single-leaf, wood door with a metal screen door.

Exterior Components

Component Component Type Material **Material Treatment**

Chimnevs Interior Slope Concrete Block Foundation Solid/Continuous Block Concrete

1-Story Full-Width Cast Metal Supports Porch No Data Block

Structural System and Concrete Masonry **Exterior Treatment**

No Data Double-hung Metal Windows Roof No Data Front Gable Asphalt

Secondary Resource Information

Secondary Resource #1

Resource Category: Domestic Resource Type: Shed NR Resource Type: Building **Date of Construction:** ca 2005 Date Source: Map

Historic Time Period: Post Cold War (1992 - Present)

Historic Context(s): Domestic Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data **Number of Stories:** 1.0 **Condition:** Fair

Threats to Resource: None Known

Architectural Description:

January 2020: There is a shed to the northeast of the house. The shed is clad in vertical wood siding and has a shed roof covered in asphalt shingles. Visible fenestration includes a single-leaf, vertical wood siding door.

Exterior Components

Component Type Material Material Treatment Component Structural System and Wood Frame Wood Vertical Board

Exterior Treatment

Roof Shed Asphalt No Data

Historic District Information

Historic District Name: No Data **Local Historic District Name:** No Data **Historic District Significance:** No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Page: 2 of 3 May 21, 2020

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5918

Project Review File Number: No Data Investigator: Erin Que

Organization/Company: The 106 Group Ltd.

Photographic Media: Digital **Survey Date:** 2/5/2020 No Data **Dhr Library Report Number:**

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

1931, 1940, Í950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

