| Property Names Name Explanation Function/Location | Name Triplex, 700 West Street | Property Evaluation Status | |
|---|----------------------------------|----------------------------|--|
| Property Addresses | | | |
| Current - 700 West Street | | | |
| County/Independent City(s): | Charlottesville (Ind. City) | | |
| Incorporated Town(s): | No Data | | |
| Zip Code(s): | 22903 | | |
| Magisterial District(s): | No Data | | |
| Tax Parcel(s): | No Data | | |
| USGS Quad(s): | CHARLOTTESVILLE EAST | | |

| Additional Property Inform | ation |
|---|---|
| Architecture Setting: | Urban |
| Acreage: | No Data |
| Site Description: | |
| January 2020: This two-story, m | ulti-family house is located on the south side of West Street on the west corner of 7th Street Street. The rear of the property provides access to a secondary dwelling on the adjacent property to the suse. |
| Surveyor Assessment: | |
| GIS Viewer 2020). However, the the 1950 Sanborn Map, suggestir of these maps, there were multipl each of these maps. It has remain | City of Charlottesville Property Records, this house was constructed in 1925 (City of Charlottesville e house and its multiple one-story wings all appear on the 1913 Sanborn Map and continue through to ng it was built c. 1910 (Sanborn Map Company 1913; Sanborn Map Company 1950). Throughout all le sheds in the rear of the property; these are no longer extant. The wraparound porch is also present in ned unchanged in aerials (USGS 1994; USGS 2017). While this building is currently multi-family licated as such on any of the Sanborn Maps (Sanborn Map Company 1929). |
| property to the west in 1958. The | ity of location and setting, with the setting mildly compromised by the construction of the adjacent integrity of design, materials, and workmanship for this property have been compromised by or material changes over time. This property retains excellent integrity of feeling and association. Integrity. |
| is located in the potential 10th & study is recommended to determinate areas of Ethnic Heritage, Commu | s not individually eligible for listing in the NRHP due to a lack of historical significance. However, it Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further ine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the unity Planning and Development, and Social History, and under Criterion C in the area of des one contributing primary resource. |
| Surveyor Recommendation: | Recommended Not Eligible |
| Ownership | |
| Ownership Category Private | Ownership Entity No Data |

| Primary Resource Information | |
|------------------------------|---|
| Resource Category: | Domestic |
| Resource Type: | Multiple Dwelling |
| NR Resource Type: | Building |
| Date of Construction: | ca 1913 |
| Date Source: | Мар |
| Historic Time Period: | Reconstruction and Growth (1866 - 1916) |
| Historic Context(s): | Domestic |
| Other ID Number: | No Data |
| Architectural Style: | Vernacular |
| | |

Virginia Department of Historic Resources

Architectural Survey Form

| Form: | No Data |
|----------------------|------------|
| Number of Stories: | 2.0 |
| Condition: | Good |
| Threats to Resource: | None Known |

Architectural Description:

January 2020: This multi-family house sits on a stuccoed foundation, is clad in stucco, and has a hipped-on-hipped roof covered in asphalt shingles. There is an interior brick chimney in the center of the roof on the ridgeline. The front (northeast) facing facade includes a one-story, full-width, open porch with a hipped roof covered in standing seam metal. The porch roof is supported by stuccoed columns with stuccoed, squared arches and the porch is accessed by a concrete step. There is a one-story, L-shaped, shed-roof addition that starts in the center of the northwest elevation and wraps around to the rear (southwest) elevation. The roof is clad in standing seam metal. On the west corner of this addition is a second-story, pyramid-roof addition covered in standing seam metal. There is a concrete chimney on the southwest end of the onestory portion of the shed-roof addition, just northeast of the two-story part. On the southeast elevation of the addition, there is a shed-roof vinyl awning above a secondary entrance. Visible fenestration includes single-leaf, wood doors with metal and glass storm doors; and one-over-one, double-hung, vinyl windows.

Exterior Components

| Component | Component Type | Material | Material Treatment |
|---------------------------------------|-----------------------|------------------|---------------------------|
| Chimneys | Interior Central | Brick | Strecther Bond |
| Foundation | Solid/Continuous | Unknown | Stuccoed/Parged |
| Porch | Wrap-Around | Stucco | Posts |
| Structural System and | Wood Frame | Unknown | Stuccoed |
| Exterior Treatment Windows Roof | Double-hung Hipped | Vinyl Asphalt | No Data No Data |

Secondary Resource Information

| Historic District Information | n |
|---------------------------------|---------|
| Historic District Name: | No Data |
| Local Historic District Name: | No Data |
| Historic District Significance: | No Data |
| | |

CRM Events

Event Type: Survey: Phase I/Reconnaissance

| Project Review File Number: | No Data |
|-----------------------------|--------------------|
| Investigator: | Erin Que |
| Organization/Company: | The 106 Group Ltd. |
| Photographic Media: | Digital |
| Survey Date: | 2/5/2020 |
| Dhr Library Report Number: | No Data |

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Virginia Department of Historic Resources Architectural Survey Form

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

