Property Names			
Name Explanation Function/Location	Name House, 714 West Street	Property Evaluation Status	
Property Addresses			
Current - 714 West Street			
County/Independent City(s):	Charlottesville (Ind. City)		
Incorporated Town(s):	No Data		
Zip Code(s):	22903		
Magisterial District(s):	No Data		
Tax Parcel(s):	No Data		
USGS Quad(s):	CHARLOTTESVILLE EAST		

Additional Property Informa	tion
Architecture Setting:	Urban
Acreage:	No Data
Site Description:	
	e is located on the south side of West Street, to the east of an alleyway that connects West Street ortheast) and southeast sides of the property are surrounded by box hedges, with a wood gate at the sts of a house and a shed.
Surveyor Assessment:	
2020). However, it first appeared of constructed c. 1925 (Sanborn Map The two-story portion has a similar	tesville Property Records, this house was constructed in 1940 (City of Charlottesville GIS Viewer on Sanborn Maps with the current footprint in 1929 as 825 West Street, indicating it was probably Company 1929; Sanborn Map Company 1950). This house has a two-story and a one-story portion. r footprint and L-Plan to a house on that lot that appears as early as the 1913 Sanborn Maps, and puse (Sanborn Map Company 1913; Sanborn Map Company 1920). The shed is a very recent als until after 2017 (USGS 2017).
	grity of location and setting. The integrity of design, materials, and workmanship has been ding, new roofing, and replacement windows. This property retains excellent integrity of feeling and retains good integrity.
is located in the potential 10th & P study is recommended to determin areas of Ethnic Heritage, Commun	not individually eligible for listing in the NRHP due to a lack of historical significance. However, it age Historic District, which is recommended as potentially eligible for listing in the NRHP. Further e if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the ity Planning and Development, and Social History, and under Criterion C in the area of es one contributing primary resource and one non-contributing secondary resource.
Surveyor Recommendation:	Recommended Not Eligible
Ownership	
<b>Ownership Category</b> Private	Ownership Entity No Data

Primary Resource Information		
<b>Resource Category:</b>	Domestic	
<b>Resource Type:</b>	Single Dwelling	
NR Resource Type:	Building	
Date of Construction:	ca 1925	
Date Source:	Мар	
Historic Time Period:	World War I to World War II (1917 - 1945)	
Historic Context(s):	Domestic	
Other ID Number:	No Data	
Architectural Style:	Vernacular	
Form:	No Data	

# Virginia Department of Historic Resources Architectural Survey Form

Number of Stories:	2.0
Condition:	Good
Threats to Resource:	None Known

#### Architectural Description:

January 2020: This two-story house sits on a stuccoed foundation, is clad in stucco, and has a hip-on-hipped roof with flared eaves, that is clad in asphalt shingles. There is an interior stuccoed chimney on the northwest ridgeline. The front (northeast) facing facade includes a one-story, full-width, open porch with a hipped roof. The porch roof is supported by decorative turned wood columns with curvy brackets on top and leafy decoration along the cornice. The porch is accessed by concrete steps. The porch wraps around to the southeast elevation and connects to a shedroof, one-story extension of the main house. The one-story wing is topped on the southwest (rear) elevation by a partial-width, second-story, front-gabled hyphen that is clad in aluminum siding. This hyphen connects to a two-story, front-gabled, aluminum-sided addition. Visible fenestration includes two-over-two, double-hung, wood windows, some with metal storm windows; a multi-lighted, textured, and stained-glass, fixed window; and a single-leaf, wood door with a metal and glass storm door.

The porch has late Victorian detailing, but overall the house does not embody an architectural style. It is not known if historic architectural details were removed from the house.

#### **Exterior Components**

Exterior Treatment Windows Double-hung Wood No Data	<b>Component</b> Chimneys Foundation Porch	Component Type Interior Slope Solid/Continuous Wrap-Around	<b>Material</b> Unknown Unknown Wood	Material Treatment Stuccoed/Parged Stuccoed/Parged Turned	
Kool nipped Metal No Data		Wood Frame Double-hung Hipped	Unknown Wood Metal	Stuccoed No Data No Data	

## **Secondary Resource Information**

### Secondary Resource #1

<b>Resource Category:</b>	Domestic
Resource Type:	Shed
NR Resource Type:	Building
Date of Construction:	ca 2018
Date Source:	Map
Historic Time Period:	Post Cold War (1992 - Present)
Historic Context(s):	Domestic
Other ID Number:	No Data
Architectural Style:	No discernible style
Form:	No Data
Number of Stories:	1.0
Condition:	Good
Threats to Resource:	None Known

### **Architectural Description:**

January 2020: There is a small shed to the southwest of this house. This shed is clad in vertical wood paneling and has a side-gabled roof that extends into an awning over the main entrance on the southwest facade. Visible fenestration includes a fixed, multi-lighted, wood window; and a single-leaf, wood door.

#### **Exterior Components**

Component	Component Type	Material	Material Treatment
Porch	Overhang/Awning	Asphalt	Not Visible
Structural System and	Wood Frame	Wood	Panels
Exterior Treatment			
Windows	Fixed	Wood	No Data
Roof	Side Gable	Asphalt	No Data

Historic District Informatio	n
Historic District Name: Local Historic District Name:	No Data No Data
Local Historic District Name:	No Dala

# Virginia Department of Historic Resources Architectural Survey Form

DHR ID: 104-5926 Other DHR ID: No Data

Historic District Significance: No Data

# **CRM Events** Event Type: Survey: Phase I/Reconnaissance **Project Review File Number:** No Data Investigator: Erin Que **Organization/Company:** The 106 Group Ltd. **Photographic Media:** Digital Survey Date: 2/5/2020 **Dhr Library Report Number:** No Data **Project Staff/Notes:** Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian **Project Bibliographic Information:** City of Charlottesville GIS Viewer 2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020. Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia. National Environmental Title Research, LLC [NETR] 1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020. Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia. Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York. United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

### **Bibliographic Information**

**Bibliography:** 

No Data

## **Property Notes:**

No Data

