Architectural Survey Form Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 718 West Street

Property Evaluation Status

DHR ID: 104-5929

Property Addresses

Current - 718 West Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This two-story house is located on the south side of West Street, to the west of an alleyway that runs from West Street to Anderson Street. There are box hedges along the northeast property line that continue along the alley to the garage. This property consists of a house and a garage.

Surveyor Assessment:

January 2020: According to City of Charlottesville Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). According to Sanborn Maps, this property replaced another two-story building on the lot, known as 827 and 829 West Street, respectively (Sanborn Map Company 1913; Sanborn Map Company 1920). The garage that is on the property today appears on Sanborn Maps in 1929 when this house was constructed (Sanborn Map Company 1929). It continues to appear in aerials until today and is likely original to the house (Sanborn Map Company 1950; NETR 1968; USGS 1994; USGS 2017).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship have been mildly compromised by replacement windows and cladding. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as potentially individually eligible for listing in the NRHP under Criterion C in the area of Architecture as a good example of the Folk Victorian architectural style in this neighborhood. Additionally, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one contributing secondary resource.

Surveyor Recommendation: Recommended Potentially Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1925

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Folk Victorian
Form: No Data

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5929

Number of Stories: 2.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: This two-story house sits on a concrete foundation, is clad in vinyl siding, and has a cross-hipped roof covered in asphalt shingles with a decorative cornice and roof brackets. There is an interior stuccoed double chimney on the southeast roof slope near the ridgeline. The front (northeast) facing facade features a one-story, full-width open porch with a hipped roof that wraps around to the southeast elevation. The porch roof is supported by turned wood columns with decorative spindlework along the cornice and brackets. The porch is accessed by concrete steps. The rear (southwest) elevation includes a one-story, partial-width wing with a hipped roof clad in standing seam metal. There is a small, shed-roof enclosed porch to the southwest of this wing. Visible fenestration includes six-over-six, double-hung, wood windows, some with metal screens; and a single-leaf wood door with a metal storm door.

Exterior Components

Component Component Type Material **Material Treatment** Stuccoed/Parged Interior Central Unknown Chimneys Uncoursed Foundation Solid/Continuous Concrete Wrap-Around Porch Wood Turned Structural System and Vinyl Wood Frame Siding Exterior Treatment

WindowsDouble-hungVinylNo DataRoofHippedAsphaltNo Data

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:GarageNR Resource Type:BuildingDate of Construction:ca 1925Date Source:Map

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: Rectangular

Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: There is a one-story garage to the southwest of the house. This shed is constructed of concrete block and has a front-gable roof covered in asphalt shingles. Visible fenestration includes a single-stall garage door of unknown material.

Exterior Components

ComponentComponent TypeMaterialMaterial TreatmentFoundationSolid/ContinuousConcreteBlockStructural System andMasonryConcreteBlock

Structural System and Masonry Concrete Block
Exterior Treatment
Roof Front Gable Asphalt No Data

Historic District Information

Historic District Name:No DataLocal Historic District Name:No DataHistoric District Significance:No Data

May 21, 2020 Page: 2 of 3

DHR ID: 104-5929 Other DHR ID: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Surveyor's NR Criteria Recommendations:

C - Distinctive Characteristics of Architecture/Construction

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

