Property Names		Property Evaluation Status	
Name Explanation Function/Location	Name House, 733 West Street	Froperty Evaluation Status	
Property Addresses			
Current - 733 West Street			
County/Independent City(s):	Charlottesville (Ind. City)		
Incorporated Town(s):	No Data		
Zip Code(s):	22903		
Magisterial District(s):	No Data		
Tax Parcel(s):	No Data		
USGS Quad(s):	CHARLOTTESVILLE EAST		

<b>Additional Property In</b>	formation		
Architecture Setting:	Urban		
Acreage:	No Data		
Site Description:			
January 2020: This two-story house is located on the north side of West Street on the east corner of 8th Street NW and West Street. There is a chain link fence surrounding the house with two concrete block piers at the main entrance on the southwest side of the property. There is also a large tree with a dilapidated wood tree house on the southeast corner of the property, and a large tree in the northwest corner. This property consists of a house and two sheds.			
Surveyor Assessment:			
Viewer). This is supported (Sanborn Map Company 1 these maps there is also a r 1963). The rear wing addit of the Coca-Cola Bottling building was residential (S	to City of Charlottesville Property Records, this house was built in 1870 (City of Charlottesville GIS I by Sanborn Maps, since the house appears unchanged from the 1913 to 1950 maps as 832 West Street 913; Sanborn Map Company 1920; Sanborn Map Company 1929; Sanborn Map Company 1950). In each of row of sheds at the rear (southeast) of the property, which were demolished between 1950 and 1963 (NETR tion was built c. 2003, according to aerial photographs (USGS 2000; USGS 2005). Up until the construction Works (104-5174) in 1939 to the north of the property off of Preston Avenue, the area to the northeast of this Sanborn Map Company 1929; Sanborn Map Company 1950). After the construction of the bottling works, tial manufacturing, as it is today (Sanborn Map Company 1950).		
to the rear of this building.	integrity of location and setting. The setting has been slightly affected by the development of manufacturing The integrity of design, materials, and workmanship for this house have been affected by replacement dding, and the rear addition. This property retains excellent integrity of feeling and association. Overall, this grity.		
This property is recommended potentially individually eligible for listing in the NRHP under Criterion A as the oldest extant property in the neighborhood. Further research is recommended to determine this property's owner and occupant history and if this was one of the first properties built in the neighborhood. Additionally, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and two non-contributing secondary resources.			
Surveyor Recommendation:	Recommended Potentially Eligible		
Ownership			

Ownership Category	<b>Ownership Entity</b>
Private	No Data

# **Primary Resource Information**

<b>Resource Category:</b>	Domestic
Resource Type:	Single Dwelling
NR Resource Type:	Building
Date of Construction:	1870
Date Source:	Local Records
Historic Time Period:	Reconstruction and Growth (1866 - 1916)

## Virginia Department of Historic Resources Architectural Survey Form

Historic Context(s):	Domestic	
Other ID Number:	No Data	
Architectural Style:	Vernacular	
Form:	Rectangular	
Number of Stories:	2.0	
Condition:	Good	
Threats to Resource:	None Known	

## Architectural Description:

January 2020: This two-story house sits on a concrete foundation, is clad in vinyl siding, and has a side-gabled roof with a centered front gable covered in asphalt shingles. The front (southwest) facing façade features a full-width, one-story, open porch with a hipped roof. The porch roof is supported by turned wood columns with decorative brackets. The porch has wood railings, and is accessed by concrete steps with wood railings. The area beneath the porch has wood latticework. The main entrance to the house is also in the center of this facade. There are three one-story, front-gabled wings on the northeast elevation that get progressively narrower. Visible fenestration includes one-over-one, double-hung, vinyl windows, some in sets of two; a fixed square and diamond stained glass window; and a single-leaf, wood door with a metal and glass storm door.

#### **Exterior Components**

Component	Component Type	Material	Material Treatment
Foundation	Solid/Continuous	Concrete	Uncoursed
Porch	1-Story Full-Width	Wood	Turned
Structural System and	Wood Frame	Vinyl	Siding
Exterior Treatment		-	-
Windows	Double-hung	Vinyl	No Data
Roof	Gable w/Central Front Gable	Asphalt	No Data

## **Secondary Resource Information**

## Secondary Resource #1

<b>Resource Category:</b>	Domestic
Resource Type:	Shed
NR Resource Type:	Building
Date of Construction:	ca 2005
Date Source:	Мар
Historic Time Period:	Post Cold War (1992 - Present)
Historic Context(s):	Domestic
Other ID Number:	No Data
Architectural Style:	No discernible style
Form:	No Data
Number of Stories:	1.0
Condition:	Fair
Threats to Resource:	None Known

#### **Architectural Description:**

January 2020: There is a one-story shed to the northeast of the house. This shed is clad in vertical wood siding and has a side-gabled roof covered in asphalt shingles. There is no visible fenestration.

### **Exterior Components**

Component	<b>Component Type</b>	<b>Material</b>	<b>Material Treatment</b>
Structural System and	Wood Frame	Wood	Vertical Board
Exterior Treatment Roof	Side Gable	Asphalt	No Data

## Secondary Resource #2

Resource Category:	Domestic
Resource Type:	Shed
NR Resource Type:	Building
Date of Construction:	ca 2015
Date Source:	Мар
Historic Time Period:	Post Cold War (1992 - Present)

## Virginia Department of Historic Resources Architectural Survey Form

Historic Context(s):	Domestic			
Other ID Number:	No Data			
Architectural Style:	No discernible style			
Form:	No Data			
Number of Stories:	1.0			
Condition:	Poor			
Threats to Resource:	None Known			
Architectural Description: January 2020: There is a sr roof.	naller, one-story shed to the ea	ast of the house. It is clad in plyw	ood vertical paneling and has a flat, corr	rugated metal
January 2020: There is a sr	naller, one-story shed to the ea	ist of the house. It is clad in plyw	ood vertical paneling and has a flat, corr	rugated metal
January 2020: There is a sr roof.	naller, one-story shed to the ea Component Type Wood Frame	nst of the house. It is clad in plyw Material Plywood/Particle Board	ood vertical paneling and has a flat, corr Material Treatment Vertical Board	rugated metal

Historic District Name:	No Data
Local Historic District Name:	No Data
Historic District Significance:	No Data

## **CRM Events**

## Event Type: Survey: Phase I/Reconnaissance

<b>Project Review File Number:</b>	No Data
Investigator:	Erin Que
Organization/Company:	The 106 Group Ltd.
Photographic Media:	Digital
Survey Date:	2/5/2020
Dhr Library Report Number:	No Data

## **Project Staff/Notes:**

Erin Que, Principal Investigator and Sr. Architectural Historian Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

## **Project Bibliographic Information:**

City of Charlottesville GIS Viewer 2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

### Hill Directory Co.

1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

National Environmental Title Research, LLC [NETR]

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services 2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS] 1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Surveyor's NR Criteria Recommendations:

# Virginia Department of Historic Resources

Architectural Survey Form

A - Associated with Broad Patterns of History

# **Bibliographic Information**

Bibliography:

No Data

**Property Notes:** 

No Data

