Architectural Survey Form

DHR ID: 104-5935 Other DHR ID: No Data

Property Information

Property Names

Name Explanation Name

Function/Location House, 800 West Street

Property Evaluation Status

Property Addresses

Current - 800 West Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This one-and-a-half story house is located on the south side of West Street on the west corner of 8th Street NW and West Street. There are box hedges lining the northeast property line, and the rear of the property is surrounded by a chain link fence. This property consists of a house and a shed.

Surveyor Assessment:

January 2020: According to City of Charlottesville Property Records, this house was constructed in 1925 (City of Charlottesville GIS Viewer 2020). The garage was constructed contemporaneously with the house, according to Sanborn Maps, since both first appear together in the 1929 and 1950 maps and remain in the same locations to today (1929 Sanborn Map Company; 1950 Sanborn Map Company).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship have been mildly compromised through replacement windows. This property retains excellent integrity of feeling and association. Overall, this property retains good integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1925

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data
Number of Stories: 1.5

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5935

Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: This one-and-a-half-story house sits on a stuccoed foundation, is clad in stucco, and has a side-gable-on-hipped roof covered in asphalt shingles. The front (northeast) facing facade features a prominent shed-roof dormer. This facade also includes a shed-roofed porch supported by stuccoed columns, that form slight arches. It also has wood railings. There is an exterior painted brick chimney on the northeast elevation. There is also a bay window on the first story of this elevation. The southwest elevation features a full-width, one-story, side-gabled wing with the same treatment as the rest of the house. There is a small enclosed porch at the east end with a shed roof that is accessed by concrete steps. The porch is clad in vertical wood siding. To the northwest of the steps, is a small front-gable wing with a door. This wing may function as a shed or an entrance to the basement of the house. The northwest elevation features a small shed-roof structure that is attached to the house. Visible fenestration includes one-over-one, double-hung, vinyl windows, some in sets of two; four-over-one, double-hung, wood windows; and a single-leaf, wood door.

Exterior Components

Component Component Type Material **Material Treatment** Exterior End Brick Strecther Bond Chimneys Stucco Dormer Shed No Data Solid/Continuous Foundation Unknown Stuccoed/Parged 1-Story Full-Width Porch Stucco Square Structural System and Wood Frame Unknown Stuccoed Exterior Treatment Windows Double-hung Vinyl No Data Roof Side Gable Asphalt No Data

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:GarageNR Resource Type:BuildingDate of Construction:1925Date Source:Map

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: Rectangular

Number of Stories: 1.0

Condition: Remodeled
Threats to Resource: None Known

Architectural Description:

January 2020: There is a one-story shed located to the northwest of the property. This shed is clad in stucco and has a side-gabled roof covered in asphalt shingles. This shed used to be a garage (Sanborn Map Company 1929). Visible fenestration includes single-leaf, wood doors; and boarded-up windows.

Exterior Components

 Component
 Component Type
 Material
 Material Treatment

 Foundation
 Solid/Continuous
 Unknown
 Stuccoed/Parged

 Structural System and Exterior Treatment
 Not Visible
 Unknown
 Stuccoed

Windows Boarded Up/Covered No Data No Data
Roof Side Gable Asphalt No Data

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form

DHR ID: 104-5935 Other DHR ID: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

