Architectural Survey Form

Other DHR ID: No Data

DHR ID: 104-5941

Property Information

Property Names

Name Explanation Name

Function/Location House, 808 West Street

Property Evaluation Status

Property Addresses

Current - 808 West Street

County/Independent City(s): Charlottesville (Ind. City)

Incorporated Town(s):No DataZip Code(s):22903Magisterial District(s):No DataTax Parcel(s):No Data

USGS Quad(s): CHARLOTTESVILLE EAST

Additional Property Information

Architecture Setting: Urban
Acreage: No Data

Site Description:

January 2020: This two-and-a-half story house is located on the south side of West Street. There are two large trees on the northwest and northeast corners of the property. Box hedges line the front (northeast) edge of the property, and there is a large evergreen tree in the westernmost corner. This property consists of a house and a shed.

Surveyor Assessment:

January 2020: According to the City of Charlottesville Property Records, this house was constructed in 1931 (City of Charlottesville GIS Viewer 2020). It first appears on the 1950 Sanborn Maps as a square-plan, brick-veneered house with an enclosed porch on the southeast side (Sanborn Map Company 1950). In 2008, a hipped roof addition was built on the southeast and southwest elevations of the building, connecting to the enclosed porch (USGS 2007; USGS 2009).

This property retains excellent integrity of location and setting. The integrity of design, materials, and workmanship have been compromised by the addition. This property retains good integrity of feeling and association. Overall, this property retains fair integrity.

This property is recommended as not individually eligible for listing in the NRHP due to a lack of historical significance. However, it is located in the potential 10th & Page Historic District, which is recommended as potentially eligible for listing in the NRHP. Further study is recommended to determine if the 10th & Page Historic District is eligible for listing in the NRHP under Criterion A in the areas of Ethnic Heritage, Community Planning and Development, and Social History, and under Criterion C in the area of Architecture. This property includes one contributing primary resource and one non-contributing secondary resource.

Surveyor Recommendation: Recommended Not Eligible

Ownership

Ownership Category Ownership Entity

Private No Data

Primary Resource Information

Resource Category:DomesticResource Type:Single DwellingNR Resource Type:BuildingDate of Construction:1931

Date Source: Local Records

Historic Time Period: World War I to World War II (1917 - 1945)

Historic Context(s): Domestic
Other ID Number: No Data
Architectural Style: Vernacular
Form: No Data
Number of Stories: 2.5

May 21, 2020 Page: 1 of 3

Architectural Survey Form Other DHR ID: No Data

DHR ID: 104-5941

Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: This two-and-a-half-story house sits on a brick foundation, is clad in stretcher bond brick, and has a side-gable roof covered in asphalt shingles. The front (northeast) facing facade includes a one-story, full-width, open porch with a hipped roof supported by tapered square brick columns with a perforated brick knee wall. The porch is accessed by brick steps. There is an exterior brick chimney in the northeast half of the northwest elevation and an exterior brick chimney in the southwest half of the southeast elevation of the original two-story house. A large one-story, mostly rectangular hipped-roof addition was built on the southeast elevation in 2008. The addition includes a one-story enclosed porch at the northeast end. This addition extends beyond the southwest elevation of the house, effectively doubling the length of the house. In the center of the rear (southwest) elevation, the addition includes a hipped roof wing for a secondary entrance. All windows on the original house have segmental arches, with stucco surrounding the windows. Visible fenestration includes four-over-one, double-hung, wood windows, some with metal storm windows; three-over-one, double-hung, wood windows, some with metal storm windows; and a single-leaf wood door with fifteen lights and a metal and glass storm door.

Exterior Components

Roof

Component Component Type Material Material Treatment Exterior End Strecther Bond Chimneys Brick Structural System and Wood Frame Brick Stretcher Bond **Exterior Treatment** Solid/Continuous Brick Stretcher Bond Foundation 1-Story Full-Width Porch Brick Columns/Posts on Piers Windows Double-hung Wood No Data

Asphalt

No Data

Secondary Resource Information

Secondary Resource #1

Resource Category:DomesticResource Type:ShedNR Resource Type:BuildingDate of Construction:ca 2006Date Source:Map

Historic Time Period: Post Cold War (1992 - Present)

Side Gable

Historic Context(s): Domestic
Other ID Number: No Data

Architectural Style: No discernible style

Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: None Known

Architectural Description:

January 2020: There is a shed to the southwest of the house. This shed is one-story and has a hipped roof covered in asphalt shingles. No other details are visible from the street.

Exterior Components

Component
RoofComponent Type
Side GableMaterial
AsphaltMaterial Treatment
No Data

Historic District Information

Historic District Name: No Data
Local Historic District Name: No Data
Historic District Significance: No Data

May 21, 2020 Page: 2 of 3

Architectural Survey Form

DHR ID: 104-5941 Other DHR ID: No Data

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: No Data Investigator: Erin Que

The 106 Group Ltd. Organization/Company:

Photographic Media: Digital **Survey Date:** 2/5/2020 **Dhr Library Report Number:** No Data

Project Staff/Notes:

Erin Que, Principal Investigator and Sr. Architectural Historian

Holly Good, Architectural Historian Saleh Miller, Sr. Architectural Historian

Project Bibliographic Information:

City of Charlottesville GIS Viewer

2020 Property Record. Electronic document, http://gisweb.charlottesville.org/GisViewer/, accessed January 27, 2020.

Hill Directory Co. 1931, 1940, 1950, 1959 Hill's Charlottesville City Directory. Hill Directory Co., Inc., Publishers, Richmond, Virginia.

1963-2016 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, http://historicaerials.com/, accessed March 19, 2020.

Neighborhood Development Services

2012-2016 The 10th and Page Historic Survey. On file at the City of Charlottesville Neighborhood Development Services, Charlottesville, Virginia.

Sanborn Map Company 1907, 1913, 1920, 1929, 1950 Fire Insurance Map of Charlottesville, Virginia. Sanborn Map Company, New York, New York.

United States Geological Survey [USGS]

1994-2019 Historical Aerial Photograph, Charlottesville Independent City, Virginia. Electronic document, accessed on Google Earth, February 20, 2020.

Bibliographic Information

Bibliography:

No Data

Property Notes:

No Data

Page: 3 of 3 May 21, 2020

