



VIRGINIA
HISTORIC LANDMARKS COMMISSION

File no. 104-72B
Negative no(s). 5073-4

SURVEY FORM

Historic name	Common name
County/Town/City	
Street address or route number	
USGS Quad	Date or period
Original owner	Architect/builder/craftsmen
Original use	
Present owner	Source of name
Present owner address	Source of date
	Stories
Present use	Foundation and wall const'n
Acreage	
	Roof type

State condition of structure and environs

State potential threats to structure
Note any archaeological interest

Should be investigated for possible register potential? yes no

Architectural description (Note significant features of plan, structural system and interior and exterior decoration, taking care to point out aspects not visible or clear from photographs. Explain nature and period of all alterations and additions. List any outbuildings and their approximate ages, cemeteries, etc.)

BRICK (FLEMISH BOND); 2 STORY; FLAT SET BACK ROOF;
14 BAYS. CONTEMPORARY. CA. 1960. ENTRANCES IN
1ST BAY WEST AND 5TH BAY EAST. FIXED CASEMENT
WINDOWS ON 2ND FLOOR

Interior inspected?

Historical significance (Chain of title; individuals, families, events, etc., associated with the property.)



SANBORN MAPS
1886: DWG.
WAGON SHED.
1891 DWG.
WAGON SHED.

Published sources (Books, articles, etc., with bibliographic data.)

Names and addresses of persons interviewed

This image shows a full page of blank graph paper. The grid consists of small, uniform squares formed by thin, light blue lines. There are no margins, text, or other markings on the paper.

This image shows a full page of blank graph paper. The grid consists of small squares formed by thin, light blue horizontal and vertical lines. There are no margins, text, or other markings on the paper.

address and title of recorder
KATE KURANDA

WPA

FEB. 20

Date _____